

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	10/15/2024	Time	08:40
		Operator Representative Park WM			
Operator Info	Park WM	Inventory ID OS2440000			
	P.O. Box 718	API Well No			
	Skiatook, OK 74070	Lease Name TBD			
	Phone: 918-288-7752	Well ID W-11			
Location	NE 22 20N 12E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.199793	Longitude	-96.008397		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection		Park WM	
Inspect No.		Date Last MIT		Last Test Result	
Casing	4.5	Tubing		USDW	
Monitoring Device Elected Monitoring Device FLM Canister Pressure Lease Status Barrel Monitor Hooked Up? Barrel Fluid Level (%) Flowline Hooked Up? Injecting	N	Tubings	Annulus	AUTHORIZED	
		Fittings	N	N	Max Pressure
		Actual Pressure		Max Volume	
		Determined?		Max Inj Units	Barrels Per Month
		Static Fluid Level			
		Determined?			
		Injection Rate (bpd)			
Inspection Comments		Inspector observed completed surface restoration at well OS2440000. Inspector previously witnessed well plugging operations on 9/9/2024.			
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.199793, -96.008397		
City: Tulsa	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010524

Orientation: NNW

Date of Photo: 10/15/2024

Time of Photo: 8:42 AM

Latitude: 36.199793

Longitude: -96.008397

Photographer: Matthew Allen

Description: This was the location of well OS2440000 after surface restoration was completed.