

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	11/12/2024	Time	11:50
		Operator Representative	Bandwheel Production Company, LLC		
Operator Info	Bandwheel Production Company, LLC P.O. Box 700426 Tulsa, OK 74170 Phone: 918-932-8418	Inventory ID	OS3259000		
		API Well No			
		Lease Name	Bandwheel		
		Well ID	CI-3		
Location	NE 13 23N 08E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.477493	Longitude	-96.391825		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Bandwheel Production Company		
Inspect No.		Date Last MIT	10/25/2011	Last Test Result	Fail
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device FLM Canister Pressure Lease Status		Fittings	N	N	Max Pressure 397
		Actual Pressure			Max Volume
		Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed post-plugging surface restoration was completed for well OS3259000. Inspector previously observed well plugging operations in accordance with the EPA approved plugging plan.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.477493, -96.391825		
City: Hominy	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010528

Orientation: S

Date of Photo: 11/29/2024

Time of Photo: 11:54AM

Latitude: 36.477493

Longitude: -96.391825

Photographer: Matthew Allen

Description: This was the location of OS3259000 at the time of the inspection. Post-plugging surface restoration was completed.