

UNLOADING SLIP

Car No. CONX 9036, 9026

On Spot No. 56

Material VF

From Dow

Received 219000

ANALYSIS

OK TO UNLOAD

UNLOADED INTO TK 202

Weights	Tank Reading
	<u>60%</u>

--	--

--	--

Date 12-14-72 By [Signature]

TUCKER 42 DTH 000004779