

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	08/16/2022	Time	11:20
Inspection Due	2019-06-05T00:00:00Z	Operator Representative	Calgary Energy, LLC		
Operator Info	Calgary Energy, LLC 4444 E. 146th St. N. Skiatook, OK 74070 Phone: 918-798-4511	Inventory ID	OS1970000		
		API Well No			
		Lease Name	Osage-Rogers		
		Well ID	2R		
Location	SE 03 28N 10E	Status	Active	Well Type	Disposal
Latitude	36.929313	Longitude	-96.212366		
Inspection Reason	Routine	Responsible Company at Time of Inspection	Calgary Energy, LLC		
Inspect No.		Date Last MIT	06/05/2017	Last Test Result	Acceptable
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 533
FLM Canister Pressure		Actual Pressure	Max Volume		
Lease Status	Active	Determined?	Max Inj Units Barrels Per Month		
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)			
Injecting	Y				
Inspection Comments	At the time of the inspection, well OS1970000 (Osage-Rogers 2R) was connected with the flowline and tubing valves open to allow injection. The well was equipped with ball valves and female fittings to allow for connection of gauges to monitor tubing and annulus pressures. The operator should install a well sign at the well. There were no areas of concern at the time of the inspection.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.929253, -96.212568		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0675

Orientation: S

Date of Photo: 8/11/2022

Time of Photo: 11:19 AM

Latitude: 36.929253

Longitude: -96.212568

Photographer: Jeanne Eckhart

Description: This was a photo showing well OS1970. The well was connected and open for injection at the time of the inspection. The well sign could not be located during the inspection.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.929253, -96.212568		
City: Pawhuska	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0676

Orientation: SE

Date of Photo: 8/16/2022

Time of Photo: 11:19 AM

Latitude: 36.929253

Longitude: -96.212568

Photographer: Jeanne Eckhart

Description: This was a photo showing a closeup view of all the valves and their position at the time of the inspection.