

Inspection Report
Mechanical Integrity Test
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas TX 75270

Inspector Matthew Allen		MIT Date 08/14/2025		Time 09:50		
Operator Representative Performance Petroleum Co		Report Sent Operator				
Inject Interval 2317 - 2800		USDW 300		Well Type Disposal		
Annulus Fluid Type water		Concentric Pkr		Packer Depth 1300		
Casing 4.5		Tubing 2.875				
Operator Info Performance Petroleum Co P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531			Inventory ID OS3557000			
			API Well No			
			Lease Name Whiting			
			Well ID SWD1			
			Location NW 11 27N 10E			
Type of MIT Ada Pressure Test			Test Reason Routine			
Injecting N		Injection Rate (bpd)		Tubular Lining		
MIT Due 12/17/2023		MIT Freq EVERY FIVE YEARS		Ann Filled (hrs)		
				Ann Press Mont		
Time		Tubing Pressure		Annulus Pressure		
Pre-Test		0		0		
Initial	10:00	610	205	Flowback	Pressure	
Mid	10:15	610	205	High	205	
Final	10:30	610	205	Mid	100	
				Low	20	
				End	0	
				Total Volume	2000	
			ADA Pressure Test - Required Test Pressure			
			(Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)			
					Tubing	Annulus
			Depth to Top Perf/Open Hole		2317	
			Depth to Fluid Level		803	
			Fluid Column Level		1514	
			Specific Gravity of Fluid		1.06	
			Nitrogen Weight Factor		1.0839	
Required Pressure Test		641.100				
Remedial Action Type						
Fluid Migration Test Type				Remedial Action Type		
Inspection Comments		Well, OS3557000 was tested with a SAPT and Ada pressure test at the same time. The calculated Ada test pressure was 641.10psi, the well achieved and maintained a test pressure of 610psi. The annulus was pressured to 205psi and maintained the pressure throughout the required 30-minute observance period. There were no areas of concern at the time of the inspection. Inspector did not record the casing size for verification.				
Inspector Signature						
Supervisor Signature						

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.836759, -96.119785		
City: Bowring	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010744

Orientation: N

Date of Photo: 8/14/2025

Time of Photo: 9:50 AM

Latitude: 36.836759

Longitude: -96.119785

Photographer: Matthew Allen

Description: This was well OS3557000 at the time of the inspection.