

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	07/30/2024	Time	11:00
		Operator Representative CapturePoint, LLC			
Operator Info	CapturePoint, LLC	Inventory ID OS4674000			
	1101 Central Expwy S.,	API Well No			
	Suite 150	Lease Name Burbank S			
	Allen, TX 75013	Well ID J-W15			
	Phone: 832-300-8221				
Location	SW 03 25N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.673477	Longitude	-96.64076		
Inspection Reason	Plugging Witnessed	Responsible Company at		CapturePoint, LLC	
		Time of Inspection			
Inspect No.		Date Last MIT	05/20/2014	Last Test Result	Fail
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 270
FLM Canister Pressure		Actual Pressure		Max Volume	
Lease Status	Active	Determined?		Max Inj Units	Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Hurricane Services squeeze 100 sacks of cement (2% calcium) at 2000psig under a packer at 1500 feet below the surface in well OS4674000. The bottom plug of 275 sacks was previously placed by the operator as part of a squeeze job to repair the well. The squeeze job which resulted in the bottom plug was part of the EPA approved workover/plugging plan.				
Inspector Signature					
Supervisor Signature					