

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/04/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Rebel Producing, LLC	
Facility Name:	Tom Lacy	
Facility Physical Location:	32.063775, -94.962285	
(city, state, zip code)	Kilgore, Texas 75652	
Mailing address:	110 FM 382	
(city, state, zip code)	Ballinger, Texas 76821	
County/Parish:	Rusk County	
Facility Phone Number	903-983-0030	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU011258	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		2 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Rebel Producing, LLC oil and gas facility located near Kilgore, Texas on 03/04/2020 for an unannounced inspection. There were no representatives of Rebel Producing, LLC present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is known as the Tom Lacy facility and has a state identification number of: RRC No. 079293.

Section II - OBSERVATIONS

I observed that the secondary containment had low berm walls. There is a drainpipe and valve used to empty the secondary containment to the woods. No damage observed.

Section III – AREAS OF CONCERN

The secondary containment was inadequate with low berm walls.

Section IV – FOLLOW UP

EPA water enforcement will refer this to EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A