

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

PLAINTIFF'S EXHIBIT

UC-3631

September 3, 1987

TO: S. J. Chanley

CC: B. D. Mollohan*
M. J. Shoger*
W. N. Stratton*

(72)

Re: SHARE Inspection Results


Dear Sara:

You will find attached a copy of the findings from the SHARE inspection held September 3, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and
2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.


S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Oct. 3, 1987)	60 Days (Nov. 3, 1987)	90 Days (Dec. 3, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: B. D. Mollohan - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment

*Copy of letter only

UCC 008479

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Page 1 of 2

Department Title Distribution Dept. No. 211 Location B 80, 75 outside RACK Date of Inspection 9-2-77

Inspector Submitting Report AH Dice Phone No. 2953 Inspection Responsibility Insulation

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		
			Action Steps or Explanation	Date Correct	Shop Ord Number
1N1	Non Asbestos At Pump & Switch Bank So. End 79 Ground Level.		Seal		
1N2	Exposed Ins. and Level So. E 79 Bldg as you go up steps At west End Perlite & Raylo		Seal		
1N3	Ins. To Eye with Needs Weather Barrier		Seal Waterproof		
1N4	Asbestos on dead line west 75	✓	Strip & Remove		
1N5	Exposed ins west End 80 outside in RACK.		Needs Weather Barrier		
1N6	Some Asbestos	✓	Remove		

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Page 2 of 2

Department Title DIST Dept. No. 211 Location Bldg 8075 Date of Inspection 9/2/87

Inspector Submitting Report H. H. Price Phone No. 2953 Inspection Responsibility INSULATION

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		Shop Order Number
			Action Steps or Explanation	Date Correct	
116	Ins. inside on 1st & 2nd level needs weather barrier		Seal		