

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 1 5									
						Year-Month-Day: 2 0 2 4 - 0 4 - 3 0									
						EPA Permit # (or RA):									
						Page 1 Of 2									
Inspector(s): Carol Chen (lead) , Carla Foy Start Time: 2:11 pm															
End Time: 2:19 pm															
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating LP)														
	Street Address: 5415 Oil Plant Rd														
	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Nature of Business: oil and gas production														
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702														
	Email:														
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319														
	O/O Mailing Address: 5415 Oil Plant Rd														
Well Data from File	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Well Name & #: St. Regis Paper Company (SRPC) #8-1 API No. 0911320025 PA No. 311581														
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: OG_511														
	Latitude (°N): 30.958033 Longitude (°W): -87.166422 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD: 15,775' ☐ Other: surface casing 10 3/4" to 3,628'														
	Smackover perforations 3 sets														
	Total Depth (ft): 15,872' Inner Casing Size (in): 8 3/4" Tubing Size (in): 4 1/2" Packer Depth (ft): 14,983'														
Field Measurements and Observations	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 15,508' Bottom(ft): 15,640' Max. Injection Pressure (psig): 7,500 psi gas N2 4,400psi PW														
	Latitude (°N): 30.968683 Longitude (°W): -87.18227 Elevation (ft):														
	EPA GPS ID: S75332 Well Status (see table): AC If not Active, Reported Date Last Active:														
	Nature of Injected Fluid(s) if any: Produced Waters (PW)														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	DANGER sign posted: H2S May Be Present..Authorized Personnel Only..Hazardous Operations..Keep Out...														
	Sign posted to identify the injection well.														
The produced waters flow line felt hot to the touch. Tubing gauge: 1600 psi															
Production gauge: 0 psi															
Surface gauge: 65 psi															
Flowline gauge:															
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN								Signature:							
Digitally signed by CAROL CHEN Date: 2024.06.20 21:23:25 -04'00'															
Version 2018-04-18															

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID EPA Well ID#: F L S 1 1 3 0 0 1 5 Year-Month-Day: 2 0 2 4 – 0 4 – 3 0 EPA Permit # (or RA): Page 2 Of 2												
Field Measurements and Observations (Cont.)	(Cont.)															
	St. Regis Paper Company (SRPC) #8-1															
	Smackover Perforations:															
	15508' to 15520', 3/10/1974															
	15581' to 15607', 4/07/1972															
	15616' to 15640', 4/07/1972															
Photo ID: RIMG0144 Time: 2:15 pm Lat (°N): 30.968702 Long (°W): -87.182255																
blurry photo of the injection tubing gauge																
Photo Log	Photographer: Carol Chen EPA Camera ID: S75332															
	Photo ID: RIMG0139 Time: 2:11 pm Lat (°N): 30.968658 Long (°W): -87.182368															
	Description: injection well, posted with well identification sign and DANGER sign: H2S May be Present...															
	Photo ID: RIMG0140 Time: 2:11 pm Lat (°N): 30.968657 Long (°W): -87.182383															
	Description: upper portion of the injection well															
	Photo ID: RIMG0141 Time: 2:13 pm Lat (°N): 30.9686 Long (°W): -87.182272															
	Description: flow line															
	Photo ID: RIMG0142 Time: 2:13 pm Lat (°N): 30.968683 Long (°W): -87.18227															
	Description: surface gauge reads 65 psi															
	Photo ID: RIMG0143 Time: 2:13 pm Lat (°N): 30.9686 Long (°W): -87.182275															
Description: production gauge reads 0 psi																
Photo ID: RIMG0144 Time: 2:14 pm Lat (°N): 30.9687 Long (°W): -87.182257																
Description: injection tubing gauge reads 1600 psi																
UIC Inspector Name: Carol Chen Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.06.20 21:23:51 -04'00'								UIC Inspector Name: Signature:								
Version 2018-04-18																