

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	K	Y	S	0	9	1	0	1	2	4
Year-Month-Day:					2	0	2	4	–	0	2	–	2	1	
EPA Permit # (or RA):					K	Y	A	0	3	6	2				
					Page		1		Of		2				
Inspector(s): Carol Chen (lead), Brianna LaPapa Start Time: 1:45 pm															
End Time: 1:50 pm															
Facility Contact Information	Facility Name: West Kentucky Energy Resources, LLC														
	Street Address: 3830 Vincent Station Drive														
	City: Owensboro County: Hancock State: KY Zip: 42303														
	Nature of Business: Oil and gas extraction														
	Facility Owner/Operator: West Kentucky Energy Resources, LLC Phone: 270-926-1689														
	Email: Glen Ridges: 270-316-7487														
	Facility Contact (if different): Vincent B. Hayden, Jr., Manager Phone: 270-683-3057														
	O/O Mailing Address: 3830 Vincent Station Drive														
Well Data from File	City: Owensboro County: Hancock State: KY Zip: 42303														
	Well Name & #: Mary Madden-Richards #W-3														
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit:														
	Latitude (°N): 37.70688 Longitude (°W): -86.71642 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	☐ Other:														
Field Measurements and Observations	Total Depth (ft): 232' Inner Casing Size (in): 7" at 219" Tubing Size (in): 2" Packer Depth (ft):														
	Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig): N/A														
	Latitude (°N): Longitude (°W): Elevation (ft):														
	EPA GPS ID: S75332 Well Status (see table): AB If not Active, Reported Date Last Active: None														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values): The Mary Madden-Richards lease is located in Reynolds Station, Kentucky, 42368.														
	Wells W-2 , W-3, W-8, are not authorized by Permit No. KYA0362. Only W-1, W-4, W-5, W-6 and W-7.														
	On 7/19/23, this well was hidden at the time, by the tall cornfield. Since the corn was removed, we can see this well now. We find no injection line anywhere. The well is disconnected. No gauges are present. We see evidence of thick, blackened crude oil, covering much of the well, in addition to circling its base, there upon the mud and brambles, just beneath.														
	See reverse for additional observations, comments and photo log														
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.03.27 16:44:20 -04'00'								Signature:							
Version 2018-04-18															

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#: K Y S O 9 1 0 1 2 4											
Year-Month-Day: 2 0 2 4 – 0 2 – 2 1																
EPA Permit # (or RA): K Y A 0 3 6 2																
Page 2 Of 2																
Field Measurements and Observations (Cont.)	(Cont.) Mary Madden-Richards #W-3															
	Photos continued...															
	Photo ID: RIMG0057 Time: 1:45 pm Lat (°N): 37.706912 Long (°W) -86.716117															
	Description: Close-up photo of injection well															
	Photo ID: RIMG0058 Time: 1:46 pm Lat (°N): 37.706873 Long (°W) -86.716358															
	Description: a different angle of the injection well															
Photo Log	Photo ID: RIMG0059 Time: 1:48 pm Lat (°N): 37.706893 Long (°W) -86.716381															
	Description: photo taken farther away from the injection well															
	Photographer: Brianna LaPapa EPA Camera ID: S75332															
	Photo ID: RIMG0051 Time: 1:37 pm Lat (°N): 37.705518 Long (°W) -86.719017															
	Description: photo of inspection report/not needed here. This well is a producer, not an injector.															
	Photo ID: RIMG0052 Time: 1:38 pm Lat (°N): 37.705518 Long (°W) -86.719017															
	Description: view of an active production well															
Photo ID: RIMG0053 Time: 1:38 pm Lat (°N): 37.705518 Long (°W) -86.719017																
Description: close-up of the producer																
Photo ID: RIMG0054 Time: 1:38 pm Lat (°N): 37.705518 Long (°W) -86.719017																
Description: just downhill of the producer, we observed a creek, very close to the producer																
Photo ID: RIMG0055 Time: 1:45 pm Lat (°N): 37.706895 Long (°W) -86.716416																
Description: photo of inspection report for Mary Madden-Richards #W-3/KYS0910124																
Photo ID: RIMG0056 Time: 1:45 pm Lat (°N): 37.706891 Long (°W) -86.71638																
Description: injection well is covered in crude oil - does not have an injection line, is disconnected																
UIC Inspector						UIC Inspector										
Name: Carol Chen						Name:										
Signature: CAROL CHEN						Signature:										
Digitally signed by CAROL CHEN Date: 2024.03.27 16:44:47 -04'00'						Version 2018-04-18										