

EPA OECA Air Enforcement Division INSPECTION REPORT

Inspection Date(s):		03/08/2023	
Media:		Air	
Regulatory Program(s)		Title II Mobile Sources	
Company Name:		Harwin Powersports	
Facility Name:		Harwin Powersports Dealership	
Facility Physical Location:		7110 Harwin Dr.	
(city, state, zip code)		Houston, TX 77036	
Mailing address:		7110 Harwin Dr.	
(city, state, zip code)		Houston, TX 77036	
County/Parish:		Harris County, TX	
Facility Contact:		Mr. Jing	Owner
		(713) 532-0505	
FRS Number:		N/A	
Identification/Permit Number:			
Media Number:		N/A	
NAICS:		N/A	
SIC:		N/A	
Facility Representatives:	Mr. Jing	Owner	(713) 532-0505
	{name}	{title}	{phone no.}
	{name}	{title}	{phone no.}
	{name}	{title}	{phone no.}
EPA Inspectors:	Mario Jorquera	OECA/OCE/AED/VEEB	202-564-1079
	Victor Aguilar	OECA/OCE/AED/VEEB	202-564-9679
	{name}	{affiliation/mailcode}	{phone no.}
State Inspector(s):	{name}	{affiliation/mailcode}	{phone no.}
	{name}	{affiliation/mailcode}	{phone no.}
Other Inspector(s):	{name}	{affiliation/mailcode}	{phone no.}
	{name}	{affiliation/mailcode}	{phone no.}
Metadata	Title:	Harwin Motorsports Dealership Houston, TX Inspection	
	Author:	Mario Jorquera	
	Subject:	Inspection Report	
	Keywords:	Inspection of nonroad motorcycle and ATV dealership	
EPA Lead Inspector Signature/Date		Mario Jorquera	MARIO
		{Inspector name}	JORQUERA
		Digitally signed by MARIO JORQUERA Date: 2023.06.09 17:31:30 -04'00'	Date
Supervisor Signature/Date		Mark Palermo	
		{Supervisor name}	Date

Section I - INTRODUCTION

PURPOSE OF THE INSPECTION

EPA HQ Air Enforcement Division, Vehicle and Engine Branch inspectors Victor Aguilar and Mario Jorquera arrived at the Harwin Motorsports dealership at 3:10 pm on March 08, 2023 for an unannounced inspection. We met with the owner, a Mr. Jing, at the front desk for the Opening Conference. We presented our credentials to Mr. Jing and informed him that this was an EPA inspection to review whether equipment available for sale at his dealership was certified by the EPA for sale in the U.S. The scope of the inspection was a compliance evaluation of several randomly selected pieces of equipment at the facility.

Mr. Jing agreed to allow EPA to conduct the requested inspections.

FACILITY DESCRIPTION

Facility is a storefront retail outlet for motorsports equipment located in a strip mall. The layout comprised of display floor space for some 50 or so vehicles, including ATVs, UTVs, karts and nonroad motorcycles, a back room for repairs and parts storage and a retail sales counter in the front.

Facility appeared to have 2 employees: The owner/manager and a mechanic.

Facility operates 6 days a week, about 9 hours each day.

Section II – OBSERVATIONS

At 3:13pm, the EPA inspectors commenced inspections.

Inspectors Mario Jorquera and Victor Aguilar conducted inspections on the following units at the dealership

- LY40MT Luyuan Moto gas Pocket Bike
- 140 FA GB Moto gas bike
- Warrior 2000 Massimo Off Highway motorcycle
- Rider Bull ATV

At 4:09 pm, inspectors Aguilar and Jorquera held a closing conference with Mr. Jing. EPA inspector Mario Jorquera informed him that everything appeared to be certified except for one of the ATVs, which did not appear to have any EPA labels. EPA identified the importer of the unlabeled ATV as Lil Pick Up (known to EPA inspectors from prior investigations).

Section III – AREAS OF CONCERN

The one ATV with no evidence of an EPA label may be uncertified for sale in the U.S. Otherwise, EPA inspectors found no noncompliance and so have no additional areas of concern.

Section IV – FOLLOW UP

EPA inspectors will check on certification status of Lil Pick Up ATV.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – Photos DSCN 1702 to DSCN1746 taken with Nikon camera on 03/08/2023