

INSPECTION REPORT
Facility Name: PHAT Daddy Transport Inc.

Attached please find the United States Environmental Protection Agency's (EPA's) inspection report of your inspected facility and/or any vehicles/engines identified therein. EPA is providing this report as a matter of agency policy and will contact you again only if needed.

Without making a determination that your business or organization is a small business, EPA is also providing you with a link to a Small Business Resources Information Sheet (<https://www.epa.gov/compliance/small-business-resources-information-sheet>) which provides an array of resources to help small businesses understand and comply with federal and state environmental laws.

Inspection Information	
Inspection Number:	3601675374-2024
Inspection Date(s):	04/24/2024
Regulatory Program(s):	Clean Air Act Title II: Mobile Source
EPA Region/Program Conducting Inspection:	U.S. EPA, Region 4 Air Enforcement Branch
Company Name:	PHAT Daddy Transport Inc.
Facility Name:	PHAT Daddy Transport Inc.
Facility Street Address:	6330 East Highway 52
Facility City, State, Zip Code:	Webb, AL 36376

Inspection Report Revision History		
Revision #	Revision Date	Reason for Revision

Inspector and Supervisor Approval

Aleeka Broner

Field Inspector Name

ALEEKA BRONER

Field Inspector Signature

Digitally signed by ALEEKA BRONER
Date: 2024.08.13 14:25:12 -04'00'

Date

Todd Groendyke

Name of Approving Official

Chief, SAES

Title

TODD GROENDYKE

Approving Official Signature

Digitally signed by TODD
GROENDYKE
Date: 2024.08.13 14:32:54 -04'00'

Date

INSPECTION REPORT

Facility Name: PHAT Daddy Transport Inc.

General Inspection Information				
Inspector(s):	Aleeka Broner, Lorianny Rivera	Inspection Date(s):	04/24/2024	
Primary Facility Representative & Title:	Bobby Phelps, Shop Foreman	Arrival/Departure Time:	10:29 a.m. EDT	1:38 p.m. EDT
Facility Contact Phone/Email:	334-792-2099	Compliance Assistance Reference Materials Provided to Facility:	Small Business Resources Information Sheet, OECA Enforcement Alert, and Exhaust System Repair Guidelines Fact Sheet	
Time Inspector(s) Presented Credentials:	10:35 a.m. EDT			
Permission to Enter Facility Granted? If Yes, by whom? If No, explain.	Yes			
	Bobby Phelps, Shop Foreman			
Photograph Range:	N/A	Photographer Name:	N/A	
Notes:				

Facility Business Activities			
Types of Services (check all that apply)		Description/Observations (types and brands of parts that are manufactured or sold, types of shop services provided, etc.)	Estimated Throughput (e.g., sales per month, installs per week)
☐	Manufactures aftermarket parts		
☐	Sells aftermarket parts		
☒	Service Shop	The facility indicated that they provide repair and maintenance services for heavy-duty fleet vehicles owned by PHAT Daddy Transport Inc. as well as other fleet companies. Services include engine swaps, oil changes, brakes, wheels, transmissions, and light repairs.	4-6 trucks are serviced per week.
☒	Fleet	PHAT Daddy Transport Inc. operates as a motor freight transportation company. There are approximately 30 trucks in the fleet. The facility indicated that more than half of the fleet vehicles are gliders.	
☐	Other		

INSPECTION REPORT

Facility Name: PHAT Daddy Transport Inc.

Personnel Interviewed			
Name	Title	Contact Info. (e.g., email, phone number)	Interviewed by (Last name of Inspector)
Bobby Phelps	Shop Foreman	334-792-2099	Broner

Documents Requested		
Document Requested	Status	Notes/Comments
List of vehicles in fleet	☒ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	List reviewed onsite by inspectors.
Service invoices for December 2021 through April 2024	☒ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	Inspectors reviewed hard copy service records on-site.
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	
	☐ Document Provided ☐ Document Request Denied ☐ Facility Agreed to Provide After Inspection ☐ Other (add notes)	

Vehicles Inspected/Observed				
VIN (last 4 digits)	EPA Engine Family	Appearance of Tampering (Yes/No/TBD)	OBD Scan Conducted? (Yes/No)	Observations
1379	Not observed	TBD	Y	Inspectors observed exterior of vehicle and utilized data logger to scan and capture vehicle's data. Inspectors did not observe emission control devices on vehicle's exhaust aftertreatment.
N/A	N/A	N/A	N	Observed the exterior of three vehicles described by the facility as gliders. Inspectors did not take photos of the vehicles.