



Applied Environmental Services
"Consultants In Wastes Management and Environmental Control"

ASBESTOS MGMT • AIR POLLUTION STUDIES • HAZARDOUS WASTE/RCRA COMPLIANCE • ENVIRONMENTAL AUDITS

4100 RIO BRAVO

SUITE 320

EL PASO, TEXAS 79902

(915) 533-4108

PLAINTIFF'S EXHIBIT

CHV-796

23 December 1987


Rafael Nickolas, Jr. President
Applied Environmental Services
716 La Cruz
El Paso, Texas 79902

Dear Mr. Nickolas:

The following sample were run for asbestos using method NIOSH 7400A:

Sample No.	Time-m	Flow-l	Fibers/cc
S-50, c-pipeway, area I removal	420	3600	0.01
S-51, c-pipeway, pers removal, area I	420	1470	0.01
S-52, c-pipeway, area I removal	150	2250	<0.01
S-53, c-pipeway, pers removal, area I	150	300	<0.01

Sincerely,


Howard G. Applegate
Ph.D.

Chevron BB
015582



Applied Environmental Services
4100 Rio Bravo Suite 320
El Paso, Texas 79902

CLIENT: DARLA ENVIRONMENTAL

PROJECT: CHEVRON

DATE: DECEMBER 22, 1987

ANALYZED BY: DR. HOWARD APPELEGATE

DATE: DECEMBER 23, 1987

SAMPLE NO.	S-50	S-51	S-52	S-53				
SAMPLE LOCATION	AREA-I "C" PIPEWAY AREA SAMPLE REMOVAL	AREA-I "C" PIPE WAY PERSONAL SAMPLE REMOVAL	AREA-I "C" PIPE WAY AREA SAMPLE REMOVAL	AREA-I "C" PIPE WAY PERSONAL SAMPLE REMOVAL				
FILTER SIZE (mm)	25	25	25	25				
START TIME	8:30 am	8:35 am	11:30 am	11:32 am				
END TIME	3:30 pm	3:35 pm	2:00 pm	2:02 pm				
RATE OF FLOW (1pm)	15	2	15	2				
TOTAL TIME (hrs)	7	7	2.5	2.5				
VOLUME SAMPLED (1)	6300	840	2250	300				
RESULTS (f/cc)	0.01	0.01	< 0.01	< 0.01				