

Class I and II Well Inspection Form
US Environmental Protection Agency – Region 4
Underground Injection Control Program
61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303
Phone: (404)562-9424

Inspection ID

EPA Well ID#:	F	L	S	1	1	3	0	0	5	0
Year-Month-Day:	2	0	2	2	-	0	9	-	1	3
EPA Permit # (or RA):							1	1	0	7
Page	1						Of	2		

Inspector(s): Page Cirillo _____ (lead), Jason Rose _____ Start Time: 7:20 AM _____
 _____, _____ End Time: 7:32 AM _____

Facility Contact Information

Facility Name: *Blackjack Plant* _____
 Street Address: *4940 Blackjack Plant Road* _____
 City: *Jay* _____ County: *Santa Rosa* _____ State: *FL* _____ Zip: *32535* _____
 Nature of Business: *Oil and gas production* _____
 Facility Owner/Operator: *Black Creek Energy, LLC* _____ Phone: *(601) 431-5386* _____
 Email: *harris.butler@butlerroyals.com* _____
 Facility Contact (if different): *Michael Wetzel* _____ Phone: *(805) 324-6271* _____
 O/O Mailing Address: *140 Virginia Street, Suite 402* _____
 City: *Richmond* _____ County: *NA* _____ State: *VA* _____ Zip: *23209* _____

Well Data from File

Well Name & #: *Black Jack Creek SWDS #1-3*
 Well Type (see table): *Disposal* _____ State Permit: API # *0911320225* _____
 Latitude (°N): *30.848162° N* _____ Longitude (°W): *-87.118922° W* _____ Elevation (ft): *193.9' (RKB)* _____
 Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing
☐ Other: _____
PBTD 6953' (w/ bit.)
 Total Depth (ft): *7003'* _____ Inner Casing Size (in): *7"* _____ Tubing Size (in): *4.5"* _____ Packer Depth (ft): *6157'* _____
 Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft): *6311'* _____ Bottom(ft): *6900'* _____ Max. Injection Pressure (psig): *1,800 psi*

Field Measurements and Observations

Latitude (°N): *30.848178° N* _____ Longitude (°W): *-87.118932° W* _____ Elevation (ft): *NA*
 EPA GPS ID: *PG No. 3358766066* _____ Well Status (see table): *SI* If not Active, Reported Date Last Active: *Operator did not provide.*
 Nature of Injected Fluid(s) if any: _____
 General Condition of the Well Site: _____

 Notes & Comments (include discrepancies from database values): *DEP indicated the disposal well is used as needed depending on when the plant is down. The operator confirmed this statement. The observed internal pressure was 0 psi. Disposal well did not appear to be operating at the time of inspection. The site was clean and well-maintained. There was no evidence of leaks or excessive corrosion.*
 Perfs (see well schematics):
3/22/1988 6311-388' DIL; 6410-6420' DIL
9/23/1983 6452-6672' DIL
12/21/1983 6796-6900' DIL

See reverse for additional observations, comments and photo log

Owner/Operator Representative (Optional)

Name: *Cliff Emmons* _____
 Signature & Date: *see attached field notes* _____

UIC Inspector

Name: *Page Cirillo* _____
 Signature & Date: *Page Cirillo* *10/07/2022*

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	5	0
	Year-Month-Day:	2	0	2	2	-	0	9	-	1	3
	EPA Permit # (or RA):							1	1	0	7
		Page 2						Of 2			

[illegible]

Photographer: Jason Rose _____ EPA Camera ID: PG camera ID no. 14 S/N:31029537 _____

Photo ID:1 _____ Time: 7:14 AM _____ Lat (°N): NA _____ Long (°W): NA _____

Description: Looking south, Black Jack Creek SWDS #1-3 sign alongside access road. _____

Photo ID:2 _____ Time: 7:17 AM _____ Lat (°N): NA _____ Long (°W): NA _____

Description: Looking south, *site overview, including well head, pressure gauges, valves, and access stairs.* _____

Photo ID:3 _____ Time: 7:18 AM _____ Lat (°N): NA _____ Long (°W): NA _____

Description: Looking south, closeup view of surface and production casing pressure gauges reading 0 psi. _____

Photo ID:4 _____ Time: 7:22 AM _____ Lat (°N): NA _____ Long (°W): NA _____

Description: Looking south, closeup view of internal pressure gauge reading 0 psi. _____

UIC Inspector

Name: Page Cirillo _____

Signature & Date: *Page Cirillo* 10/07/2022

Site Photographs
Blackjack Creek SWDS #1-3:
September 13, 2022



Photograph 1: Looking south, Blackjack Creek SWDS #1-3 sign alongside access road.



Photograph 2: Looking south, site overview, including well head, pressure gauges, valves, and access stairs.



Photograph 3: Looking south, closeup view of surface casing pressure gauge (0 psi) and production casing pressure gauge (0 Psi).



Photograph 4: Looking west, closeup view of internal pressure gauge reading 0 psi.