

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	09/20/2022	Time	09:30
Inspection Due	2019-01-17T00:00:00Z	Operator Representative	CapturePoint, LLC (formerly Perdure Petroleum, LLC)		
Operator Info	CapturePoint, LLC (formerly Perdure Petroleum, LLC) 1101 Central Expwy S., Suite 150 Allen, TX 75013 Phone: 832-300-8221	Inventory ID	OS0406000		
		API Well No			
		Lease Name	North Burbank Unit		
		Well ID	60-W25		
Location	NW 30 27N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.795397	Longitude	-96.707127		
Inspection Reason	Fluid Level Monitoring	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT	10/13/1999	Last Test Result	Acceptable
Casing	4.5	Tubing	2.375	USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	Y	Y	Max Pressure 803
FLM Canister Pressure		Actual Pressure	0	0	Max Volume
Lease Status		Determined?	Other	Open Value	Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?	Echo Meter		
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	At the time of the inspection, the operator reported the casing of well OS0406000 was parted approximately 90 feet below the surface. At the time of the inspection, I observed the fluid level down the tubing and the casing to be at 98.70 feet with the EPA Echometer. At the time of the inspection, I observed 0 psi pressure on the casing and tubing of the well.				
Inspector Signature	MATTHEW ALLEN Digitally signed by MATTHEW ALLEN DN: c=US, o=U.S. Government, ou=Environmental Protection Agency, cn=MATTHEW ALLEN, 0.9.2342.19200300.100.1.1=68001004162907 Date: 2022.09.30 15:13:33 -05'00'				
Supervisor Signature	JEANNE ECKHART Digitally signed by JEANNE ECKHART Date: 2022.10.05 08:46:04 -05'00'				

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.795397, -96.707127		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0804

Orientation: n/a

Date of Photo: 09/20/2022

Time of Photo: 9:29 AM

Latitude: 36.795397

Longitude: -96.707127

Photographer: Matthew Allen

Description: This was the well sign for well OS0406000 (NBU 60-W25).



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.795397, -96.707127		
City: Shidler	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN0805

Orientation: E

Date of Photo: 09/20/2022

Time of Photo: 9:30 AM

Latitude: 36.795397

Longitude: -96.707127

Photographer: Matthew Allen

Description: This was well OS0406000.