

Region 6 - Enforcement & Compliance Assurance Division

INSPECTION REPORT

Inspection Date(s):	1/8/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Unknown	
Facility Name:	Unknown	
Facility Physical Location:	36.709255, -96.473608	
(city, state, zip code)	Pawhuska, Oklahoma 74056	
Mailing address:	Unknown	
(city, state, zip code)	Unknown	
County/Parish:	Osage County	
Facility Phone Number	Unknown	
Facility Contact:	Unknown	
	Unknown	
FRS Number:	N/A	
Identification/Permit Number:	N/A	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		28 FEB 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Unknown trash dump site located near Blackwell, Oklahoma on 01/08/2020 for an unannounced inspection. There were no representatives present during the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This inspection was in response to a complaint near a creek and pasture west of Pawhuska, Oklahoma, north off Highway 60. EPA received an anonymous complaint of household and construction trash being dumped in a tributary of Bird Creek.

Section II - OBSERVATIONS

I observed that trash, including building materials and appliances, had been piled into a running creek or tributary of Bird Creek.

Section III – AREAS OF CONCERN

Trash was observed in a flowing creek channel that leads to Bird Creek.

Section IV – FOLLOW UP

EPA water enforcement referred this site to the Oklahoma Department of Environmental Quality and Bureau of Indian Affairs.

Section V – LIST OF APPENDICES

N/A