

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	3/04/2020	
Media Program:	Water	
Regulatory Program(s)	Brine - CWA	
Company Name:	Falcon Resources, Inc.	
Facility Name:	Mayfield-Alford Lease	
Facility Physical Location:	32.195062, -94.928867	
(city, state, zip code)	Kilgore, Texas 75662	
Mailing address:	1100 Stone Rd., Ste.118	
(city, state, zip code)	Kilgore, Texas 75662	
County/Parish:	Rusk County	
Facility Phone Number	903-983-5333	
Facility Contact:	Main Office	
FRS Number:	N/A	
Identification/Permit Number:	TXU011260	
Media Identifier Number:	N/A	
NAICS:	21111	
SIC:	1311	
Personnel participating in inspection:		
Kent W. Sanborn	EPA 6 ECDWE	Environmental Engineer
EPA Lead Inspector Signature/Date		
	Kent W. Sanborn	Date
Supervisor Signature/Date		2 APR 2020
	Guy Tidmore	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Falcon Resources, Inc. oil and gas facility located near Kilgore, Texas on 03/04/2020 for an unannounced inspection. There were no representatives of Falcon Resources, Inc. present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

This facility is on the Mayfield-Alford Lease. The state identification number is: RRC No. 08640.

Section II - OBSERVATIONS

The secondary containment berms were eroded and flat during the inspection. There is a drain valve on the secondary containment but no brine damage observed outside the containment.

Section III – AREAS OF CONCERN

There was no secondary containment during the inspection.

Section IV – FOLLOW UP

EPA water enforcement will refer this to EPA Region 6 SPCC program.

Section V – LIST OF APPENDICES

N/A