


0007-SWP-000006940

Print No. MSW-182

by
MEMO 24
T. H. ST
T. H. ST

Received



0007-SWP-000006941

N12874.01

0007-SWP-000006942

Photo by

William M.
RITTASE

247 515th St

W. Va.

Phone


For 1953

P.M. H. MSW.163

No. 4 - Putting the buckles into
corroding jars.

7

74



0007-SWP-000006943

N12874.02

0007-SWP-000006944

Photo by

William M
RITASE

207 Fifth St


Union Pa

Phone

RA 1219

No. 8 - Lead grinding Mill.

Print No. *MSW.178*



0007-SWP-000006945

N12874.03

No. 9 - Lead grinding mill with linseed oil

0007-SWP-000006946

Photo by

William M

RITTSB

247 S 15th St


Phila Pa

Phone

Pen 1936

Print No. *MSW-192A*

Sharon - Wms



0007-SWP-000006947

Photo by

WILLIAM M.
RATNER SE

247 SICH ST

PHILA Pa

PL 20


PL 100

Print No. MSW.160

No. 5 - Operators unloading a stack

Sherrin Wro

0007-SWP-000006948



N12874.05

0007-SWP-00

FILE NO. *100-100000*

Date Received *12-4-41*

Half Price *100-100000*

Zinc *100-100000*

Appears in *100-100000*


PROPERTY OF
 ADVERTISING DEPT. THE SHERWIN-WILLIAMS CO.
 100 CANAL ROAD
 CLEVELAND, OHIO

RETURN TO
 THE SHERWIN-WILLIAMS CO.
 100 CANAL ROAD
 CLEVELAND, OHIO
 FILE NO. *100-100000*

WL-13

12-4

*We had Spaulding - Spaulding
 at 6 p.m.*




0007-SWP-000006951

N12874.06

Big lead melting oven.
Manufacture of W. H. Lead.
Chicago

WL-8





0007-SWP-000006953

N12874.07


The Old Dutch Corroding duck ally.
Through the open doorway above
and a little to the left of the
fire plug can be seen piles of
pig lead ready to go through the
plant. ~~There~~ - Chicago

Photo rec'd July 1934.
Record Print # 920947

947

Ent made for 1936 SWP Buffalo. exp. 1934

W 3a-5



0007-SWP-000006955

N12874.08


White's Lead corroding bucket
And lead buckles.

Record Print # 0544

WL-3 D

544





0007-SWP-000

5 Loading the Lead Buckles into
the corroding pots.

Chicago White Lead Works
used in B-592-The Truth About
House Paint Book Page 8.

Record Print #C-29484-B

WL - 47
1-42

69



0007-SWP-000006959

White Lead

WL-2 A


1. Loading the lead buckles into the corroding pots.
2. Corroding pot.
3. Corroded lead buckle and before corroding.
4. Taking the buckles after corroding for 90 days.
5. Top of full stack in full blast showing steam generated by heat of decomposing fuel.
6. View in the Red Lead Division.

Record Book # 8-0787

787

cut made for 8-642 - January 1934.

0007-SWP-000006960



NI2874.11


W.L. # 20
16-42

Handwritten notes, possibly "Handwritten" and "16-42".

Read 1000 540-769
" " 540 1599

1599

0007-SWP-000006962



0007-SWP-000006963

N12874.12

WL-2B


White Lead

7. Runway through the Carter White Lead division, corroding cylinders below.
8. General view of the Leadbuckle casting machine.
9. Filling kegs with ODP White Lead.
10. A political cartoon showing a stock of Sherwin-Williams Old Dutch Process White Lead needed to supply our customers.
11. Capping steel lead kegs.

Record Print # 790797

797

Cut made for E-642 - January 1934.




0007-SWP-000006965

White lead. Starts to
corrode at Chicago
White Lead Plant.

Photo taken 1928.
Stack steaming under
full load.

Record Print # - 29484-I



WL-141