

## Region 6 - Enforcement & Compliance Assurance Division

### INSPECTION REPORT

|                                        |                                           |                               |
|----------------------------------------|-------------------------------------------|-------------------------------|
| Inspection Date(s):                    | 3/4/2025                                  |                               |
| Media Program:                         | Water                                     |                               |
| Regulatory Program(s)                  | Clean Water Act                           |                               |
| Company Name:                          | <b>Weiser-Brown Operating Company</b>     |                               |
| Facility Name:                         | <b>RB Allen No. 1 SWD</b>                 |                               |
| Facility Physical Location:            | Latitude: 33.420941 Longitude: -92.021094 |                               |
| (city, state, zip code)                | Stephens, AR, 71764                       |                               |
| Mailing address:                       | 117 East Calhoun                          |                               |
| (city, state, zip code)                | Magnolia, AR 71753                        |                               |
| County/Parish:                         | Ouachita County                           |                               |
| Facility Phone Number                  | 870-234-3839                              |                               |
| Facility Contact:                      | Chris Weiser<br>chrisw@weiser-brown.com   |                               |
| FRS Number:                            | NA                                        |                               |
| Identification/Permit Number:          | ARU002295                                 |                               |
| Media Identifier Number:               | NA                                        |                               |
| NAICS:                                 | 211111                                    |                               |
| SIC:                                   | 1311                                      |                               |
| Personnel participating in inspection: |                                           |                               |
| Michael Blaha (lead)                   | EPA/Region 6 ECDW                         | Enforcement Officer/Inspector |
| Kerri McCabe                           | EPA/Region 6 ECDW                         | Enforcement Officer/Inspector |
|                                        |                                           |                               |
|                                        |                                           |                               |
|                                        |                                           |                               |
|                                        |                                           |                               |
|                                        |                                           |                               |
|                                        |                                           |                               |
|                                        |                                           |                               |
|                                        |                                           |                               |
|                                        |                                           |                               |
|                                        |                                           |                               |
| EPA Lead Inspector<br>Signature/Date   |                                           |                               |
|                                        | Michael Blaha                             | Date                          |
| Supervisor<br>Signature/Date           |                                           |                               |
|                                        | Jeanne Eckhart                            | Date                          |

## **Section I – INTRODUCTION**

### **PURPOSE OF THE INSPECTION**

EPA Region 6 inspectors Michael Blaha and Kerri McCabe arrived at Weiser-Brown Operating Company – RB Allen No. 1 SWD, located off Ouachita Road 8 (33.420941, -93.021094) at 1:50 PM on March 4, 2025, for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

### **FACILITY DESCRIPTION**

EPA conducted an inspection on the Weiser-Brown Operating Company – RB Allen No. 1 SWD, which consists of one (1) saltwater tank, and one (1) injection well.

## **Section II - OBSERVATIONS**

I observed the facility sign, secondary containment, pipes, valves, and storage tanks located at the facility; see Appendix 1 (photo log), photo No. 1 and No. 2. For additional GPS location and photo metadata, see Appendix 1.

## **Section III – AREAS OF CONCERN**

No closing conference was held due to no Weiser-Brown Operating Company staff being present during the inspection. No areas of concern were identified at the time of inspection.

## **Section IV – FOLLOW UP**

Inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure areas of concern are properly addressed.

## **Section V – LIST OF APPENDICES**

Appendix 1 – Photo Log – 2 photos taken on 3/4/2025

## Appendix 1

### Photograph Log

#### 2 Photos



## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

### Photograph Log

Photo No. 1

|                                 |                         |                 |
|---------------------------------|-------------------------|-----------------|
| Location: 33.420941, -93.021094 |                         |                 |
| City: Stephens                  | County/Parish: Ouachita | State: Arkansas |



**Photo File Name:** 20250304\_195330792\_iOS

**Orientation:** W

**Date of Photo:** 3/4/2025

**Time of Photo:** 1:53 PM

**Latitude:** 33.420941

**Longitude:** -93.021094

**Photographer:** Michael Blaha

**Description:** This photo was taken looking west and shows the facility sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

## Photograph Log

Photo No. 2

|                                 |                         |                 |
|---------------------------------|-------------------------|-----------------|
| Location: 33.420941, -93.021094 |                         |                 |
| City: Stephens                  | County/Parish: Ouachita | State: Arkansas |



**Photo File Name:** 20250304\_195415977\_iOS

**Orientation:** W

**Date of Photo:** 3/4/2025

**Time of Photo:** 1:54 PM

**Latitude:** 33.420922

**Longitude:** -93.021011

**Photographer:** Michael Blaha

**Description:** This photo was taken looking west and shows an overview of the facility.