

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	K	Y	S	0	9	9	0	0	0	4
Year-Month-Day:					2	0	2	4	–	0	2	–	2	1	
EPA Permit # (or RA):					K	Y	I	0	3	8	9				
					Page		1		Of		2				
Inspector(s): Carol Chen (lead), Brianna LaPapa Start Time: 9:24 am															
End Time: 9:32 am															
Facility Contact Information	Facility Name: Logsdon Valley Oil Co., Inc.														
	Street Address: 105 Bedford Court														
	City: Horse Cave County: Hart State: KY Zip: 42749														
	Nature of Business: Oil and gas extraction														
	Facility Owner/Operator: Logsdon Valley Oil Co., Inc. Phone: 270-537-4288														
	Email: estinson@scrtc.com														
	Facility Contact (if different): Ellen Stinson, President Phone: 270-537-4288														
	O/O Mailing Address: 105 Bedford Court														
	City: Horse Cave County: Hart State: KY Zip: 42749														
Well Data from File	Well Name & #: Guinn #UA-3														
	Well Type (see table): Enhanced Oil Recovery (EOR) State Permit: 77804														
	Latitude (°N): 37.177528 Longitude (°W): -85.78917 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD: ☐ Other: surface casing 130 feet deep, 8¼" hole														
	Total Depth (ft): 627' Inner Casing Size (in): 4½" 625' Tubing Size (in): 4¾" Packer Depth (ft):														
	Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig):														
Field Measurements and Observations	Latitude (°N): 37.175278 Longitude (°W): -85.789167 Elevation (ft):														
	EPA GPS ID: S75322 Well Status (see table): IN If not Active, Reported Date Last Active: 3/17/16														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	In preparation for the upcoming plugging and abandonment of Guinn #UA-3, a mobile workover rig was placed onsite with a cable tool to insert a sucker rod into the injection well's														
	production casing for cementation.														
Owner/Operator Representative (Optional)								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.03.27 18:51:35 -04'00'								Signature:							
Version 2018-04-18															

Inspection ID	EPA Well ID#:	K	Y	S	0	9	9	0	0	0	4
	Year-Month-Day:	2	0	2	4	-	0	2	-	2	1
	EPA Permit # (or RA):	K	Y	I	0	3	8	9			
Page							2	Of		2	

[illegible]

Photographer: Brianna LaPapa EPA Camera ID: S75332

Photo ID: RIMG009 Time: 9:27 am Lat (° N): 37.175344 Long (° W): -85.789128

Description: tank battery and truck-mounted mobile workover rig at injection well

Photo ID: RIMG010 Time: 9:27 am Lat (° N): 37.175278 Long (° W): -85.789167

Description: injection well, sucker rod in casing

Photo ID: RIMG011 Time: 9:34 am Lat (° N): 37.175355 Long (° W): -85.789153

Description: workover rig over injection well

Photo ID: RIMG012 Time: 9:34 am Lat (° N): 37.175342 Long (° W): -85.789158

Description: closer view of workover rig and injection well

Photo ID: _____ Time: _____ Lat (° N): _____ Long (° W): _____

Description: _____

UIC Inspector	
Name: _____	
Signature: _____	