

## **ROLLING LADDERS BRAKE LININGS**

### **MATERIAL IDENTIFICATION**

The P-299411 brake lining contains asbestos and is part of the 2A brake assembly. This referenced piece part is included in the brake shoe sub-assembly of 2A brake assemblies incorporated in some rolling ladders.

Note that an exposure assessment and personal monitoring may be warranted. Contact your functional environment and safety organization to arrange for this before work begins.

### **PERSONAL PROTECTIVE EQUIPMENT**

1. Tyvek suit, with hood and booties
2. Safety glasses
3. Latex gloves
4. Respirator (if exposure assessment warrants)

### **EQUIPMENT AND SUPPLIES**

1. HEPA vacuum
2. Polyethylene, 6 mil
3. Amended water in spray bottles
4. Asbestos disposal bags
5. Asbestos warning flagging or other means to cordon off the area

### **SITE PREPARATION**

1. Cordon off the work area
2. Place plastic on floor, extending at least 6 feet all around the work area

### **WORK PROCEDURES**

1. Wet the lining, before removing.
2. Place all removed asbestos containing parts in asbestos disposal bag.
3. Follow all decontamination and waste disposal procedures.