

**Region 6 Enforcement and Compliance Assurance Division
INSPECTION REPORT**

Inspection Date(s):	10/29/2019		
Media:	Water		
Regulatory Program(s)	Brine - CWA		
Company Name:	Marlin Oil Corporation		
Facility Name:	Alma Rogers Lease		
Facility Physical Location:	36.542995, -96.263457 (Sect. 30, T 24N, R 10E)		
(city, state, zip code)	Wynona, Oklahoma 74084		
Mailing address:	P.O. Box 49		
(city, state, zip code)	Wynona, Oklahoma 74084		
County/Parish:	Osage County		
Facility Contact:	Bruce Marlin		
	580-716-6025		
FRS Number:	N/A		
Identification/Permit Number:	N/A		
Media Number:	N/A		
NAICS:	21111		
SIC:	1311		
Personnel participating in inspection:			
Kent W. Sanborn	6ECDWE	Environmental Engineer	(918) 557 – 1615
EPA Lead Inspector Signature/Date			
	Kent W. Sanborn		Date
Supervisor Signature/Date			19 NOV 2019
	Guy Tidmore		Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspector K.W. Sanborn visited the Marlin Oil Corporation oil and gas facility located at latitude 36.542995 and longitude -96.263457 near Wynona, Oklahoma on 10/29/2019 for an unannounced inspection. There were no representatives of Marlin Oil Corporation present for the inspection. The inspection was conducted by authority of the Clean Water Act and the Safe Drinking Water Act to determine compliance with the Environmental Protection Agency (EPA) regulations.

FACILITY DESCRIPTION

The facility is known as the Alma Rogers lease and is east of Wynona, Oklahoma.

Section II - OBSERVATIONS

I observed low secondary containment berms during the inspection. There was surface damage outside the tank battery on the west side as well. The shallow secondary containment pit had fluids in it during the inspection.

Section III – AREAS OF CONCERN

The secondary containment was too low.

Section IV – FOLLOW UP

EPA water enforcement will refer this facility to EPA SPCC program.

Section V – LIST OF APPENDICES

N/A