

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	08/01/2024	Time	11:00
		Operator Representative	Calgary Energy, LLC		
Operator Info	Calgary Energy, LLC 4444 E. 146th St. N. Skiatook, OK 74070 Phone: 918-798-4511	Inventory ID	OS0813000		
		API Well No			
		Lease Name	Crossland		
		Well ID	2		
Location	SW 04 22N 07E	Status	Inactive	Well Type	Disposal
Latitude	36.410663	Longitude	-96.5604		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	Calgary Energy, LLC		
Inspect No.		Date Last MIT	03/05/1986	Last Test Result	Acceptable
Casing	5.5	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 690
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status	Inactive	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed Calgary Energy, LLC tag the top of the bottom cement plug at 2280 feet below the surface then fill the well with mud to 375 feet below the surface. The bottom plug was set by Calgary and witnessed by EPA and BIA on 7/30/2024. Calgary Energy, LLC perforated the casing at 374 and 166 feet below the surface, then circulated 100 sacks of class A cement to the surface from 375 feet.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.410663, -96.5604		
City: Blackburn	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010501

Orientation: NE

Date of Photo: 08/01/2024

Time of Photo: 12:41 PM

Latitude: 36.410663

Longitude: -96.5604

Photographer: Matthew Allen

Description: This was well OS0813000 with cement circulating to the surface.