

Inspector	Matthew Allen			MIT Date	06/26/2024		Time	09:15	
Operator Representative	Performance Energy Resources, LLC			Report Sent Operator					
Inject Interval	1710 - 1745			USDW	397		Well Type	Disposal	
Annulus Fluid Type	Water			Concentric Pkr		Packer Depth		1635	
Casing	4.5			Tubing	2.375				
Operator Info	Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531				Inventory ID	OS1606000			
					API Well No				
					Lease Name	PRICE			
					Well ID	2W			
					Location	NE 30 25N 11E			
Type of MIT	Casing - Tubing Annulus Pressure				Test Reason	Routine			
Injecting	Y		Injection Rate (bpd)		Tubular Lining	Ann Filled (hrs)			
MIT Due	12/17/2023		MIT Freq		EVERY FIVE YEARS		Ann Press Mont		
Time	Tubing Pressure	Annulus Pressure		Flowback	Pressure	Volume			
Pre-Test	-30	0		High	190				
Initial	09:15	-30	200	Mid	100	1000			
Mid	09:30	-30	195	Low	20	1000			
Final	09:45	-30	190	End	0	700			
				Total Volume		2700			
				ADA Pressure Test - Required Test Pressure (Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)					
						Tubing	Annulus		
				Depth to Top Perf/Open Hole					
				Depth to Fluid Level					
				Fluid Column Level					
				Specific Gravity of Fluid					
				Nitrogen Weight Factor					
				Required Pressure Test					
				Remedial Action Type					
Fluid Migration Test Type				Remedial Action Type					
Inspection Comments	MIT conducted. Pressure hold OK.								
Inspector Signature									
Supervisor Signature									

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.618607, -96.160114		
City: Barnsdall	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010449

Orientation: WSW

Date of Photo: 6/26/2024

Time of Photo: 9:15 AM

Latitude: 36.618607

Longitude: -96.160114

Photographer: Matthew Allen

Description: This was the well sign for well OS1606000.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.618607, -96.160114		
City: Barnsdall	County/Parish: Osage	State: Oklahoma




Photo File Name: R0010450

Orientation: WNW

Date of Photo: 6/26/2024

Time of Photo: 9:15 AM

Latitude: 36.632221

Longitude: -96.128087

Photographer: Matthew Allen

Description: This was well OS1606000 at the time of the inspection. The well was connected.