

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

July 22, 1987

[Handwritten signature]

PLAINTIFF'S EXHIBIT

UC-3627

TO: U. R. Stokely

CC: S. W. Drake*
M. J. Shoger*

Re: SHARE Inspection Results

Dear Dave:

You will find attached a copy of the findings from the SHARE inspection held July 22, 1987. Thank you for the cooperation of your staff and hourly folks in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and
2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

[Handwritten signature: S. B. Kovach]
S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Aug. 22, 1987)	60 Days (Sep. 22, 1987)	90 Days (Oct. 22, 1987)
% Complete	70%	76%	90%
Signature	<i>[Handwritten signature: S. W. Drake]</i> 8/21/87	<i>[Handwritten signature: S. W. Drake]</i> 9/30/87	<i>[Handwritten signature: S. W. Drake]</i> 10/26/87
Send copy of update to:	S. W. Drake - Bldg. 82-3 S. B. Kovach - Bldg. 109-2		

SBK/yc
1658A

Attachment

*Copy of letter only

UCC 008467

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Page 1 of 2

Department: Chemical Mix Dept. No. 049 Location 323 Date of Inspection 7/22/87
 Inspector Sub-
 mitting Report H.H. Price Phone No. 2953 Inspection Responsibility Insulation Date of Report 7/22/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		
			Action Steps or Explanation	Date Correct	Shop Order Number
1N1	Exposed Ins between 3056 & 3061 Tanks ✓ 3066.		Seal		
			Asbestos Insulation Removed	9/24/87	
1N2	Exposed Ins in Rack going to Tank Car Load FAC. between Tank 2063 & 2064 & Tank Car Load FAC.	✓	Patch & Seal		
			Asbestos Insulation Removed	9/24/87	
1N3	Exposed Tank in Rack West Tank 2014 & on Ground	✓	Patch - Seal		
			Work Started		
			Insulation Removed	10/22/87	
1N4	Not Following Color Code for Asbestos Free ins.	✓			
1N5	Asbestos Free Sign Reads Asbestos Insulation	✓	Follow Color Code		
			Covered	10/22/87	

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Page 2 of 2

Department Title: Environmental Mgr Dept. No.: 049 Location: 535 Date of Inspection: 7/23/87

Inspector Submitting Report: H.H. Price Phone No.: 2953 Inspection Responsibility: Insulation Date of Report: 7/23/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan		
			Action Steps or Explanation	Date Correct	Shop Order Number
1N6	Exposed Ins. in Rack	✓	Patch & Seal		
	North & South East 325		WORK STAGE		
			INSULATION REMOVED	10/14/87	
1N7	Exposed Ins. in Rack Running East & West Along Rd.	✓	Patch Seal		
			Strip		
			INSULATION REMOVED	10/14/87	
1N8	Exposed Ins. Over head in 325 Over head	✓	Patch & Seal		
			WORK STAGE		
			PATCHED AND SEALED	10/14/87	
1N9	Exposed Asbestos	✓	Strip Patch Seal		
			INSULATION REMOVED	10/14/87	
			WORK STAGE		
1N10	Exposed ins. Tank Cover	✓	Patch & Seal		
	Lead Rack So. side 325 drum				
	on S.E. side		WORK STAGE		