

Inspector	Matthew Allen			MIT Date	06/26/2024		Time	10:00	
Operator Representative	Performance Energy Resources, LLC			Report Sent Operator					
Inject Interval	1748 - 1778			USDW	240		Well Type	Disposal	
Annulus Fluid Type	Water			Concentric Pkr		Packer Depth		1675	
Casing	4.5			Tubing	2.375				
Operator Info	Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531				Inventory ID	OS5624000			
					API Well No				
					Lease Name	QUAPAW			
					Well ID	200			
					Location	NW 21 25N 11E			
Type of MIT	Casing - Tubing Annulus Pressure				Test Reason	Routine			
Injecting	Y		Injection Rate (bpd)		Tubular Lining		Ann Filled (hrs)		
MIT Due	08/30/2022		MIT Freq		EVERY FIVE YEARS		Ann Press Mont		
Time	Tubing Pressure	Annulus Pressure		Flowback	Pressure		Volume		
Pre-Test	0	0		High	200				
Initial	10:00	0		Mid	100		1400		
Mid	10:15	0		Low	20		1400		
Final	10:30	0		End	0		500		
				Total Volume		3300			
				ADA Pressure Test - Required Test Pressure (Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)					
				Depth to Top Perf/Open Hole					
				Depth to Fluid Level					
				Fluid Column Level					
				Specific Gravity of Fluid					
				Nitrogen Weight Factor					
				Required Pressure Test					
				Remedial Action Type					
Fluid Migration Test Type				Remedial Action Type					
Inspection Comments									
Inspector Signature									
Supervisor Signature									

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.632221, -96.128087		
City: Barnsdall	County/Parish: Osage	State: Oklahoma




Photo File Name: R0010451

Orientation: W

Date of Photo: 6/26/2024

Time of Photo: 10:01 AM

Latitude: 36.632221

Longitude: -96.128087

Photographer: Matthew Allen

Description: This was the well sign for well OS5624000.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.632221, -96.128087		
City: Barnsdall	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010452

Orientation: W

Date of Photo: 6/26/2024

Time of Photo: 10:03 AM

Latitude: 36.632221

Longitude: -96.128087

Photographer: Matthew Allen

Description: This was well OS5624000 at the time of the inspection. The well was connected.