

Inspection Report
Mechanical Integrity Test
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas TX 75270

Inspector Matthew Allen		MIT Date 08/13/2025		Time 10:00		
Operator Representative Performance Energy Resources, LLC		Report Sent Operator				
Inject Interval 1568 - 1640		USDW 260		Well Type Dual Completion		
Annulus Fluid Type Casing 4.5		Concentric Pkr Tubing 2.375		Packer Depth 1568		
Operator Info Performance Energy Resources, LLC P.O. Box 628 Barnsdall, OK 74002 Phone: 918-847-2531			Inventory ID OS4909000			
			API Well No			
			Lease Name STAPLETON			
			Well ID 12 SWD			
			Location NE 21 24N 11E			
Type of MIT Ada Pressure Test			Test Reason Routine			
Injecting N		Injection Rate (bpd)		Tubular Lining		
MIT Due 04/06/2024		MIT Freq EVERY FIVE YEARS		Ann Filled (hrs)		
				Ann Press Mont		
Time		Tubing Pressure		Annulus Pressure		
Pre-Test		0				
Initial 10:15		200		Flowback High		
Mid 10:30		200		Mid		
Final 10:45		200		Low		
				End		
				Total Volume		
			ADA Pressure Test - Required Test Pressure			
			(Fluid Column Ht * Specific Gravity * .433 / N2 Wt Fac = Required Test Pressure)			
					Tubing	Annulus
			Depth to Top Perf/Open Hole		1568	
			Depth to Fluid Level		0	
			Fluid Column Level		1568	
			Specific Gravity of Fluid		1.06	
			Nitrogen Weight Factor		1.0576	
			Required Pressure Test		680.480	
			Remedial Action Type			
Fluid Migration Test Type				Remedial Action Type		
Inspection Comments		Well, OS4909000 failed to achieve the required test pressure of 680.48psi. The well achieved a pressure of 200psi.				
Inspector Signature						
Supervisor Signature						

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.5461, -96.13195		
City: Barnsdall	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010743

Orientation: N

Date of Photo: 8/13/2025

Time of Photo: 10:08 AM

Latitude: 36.5461

Longitude: -96.13195

Photographer: Matthew Allen

Description: This was well OS4909000 at the time of the inspection.