

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date(s):	12/12/2023	
Media Program:	Water	
Regulatory Program(s)	Clean Water Act	
Company Name:	Neilco (4063) 3G Energy	
Facility Name:	Frost F3 Tank Battery	
Facility Physical Location:	Latitude: 33.2465, Longitude: -92.60204	
(city, state, zip code)	El Dorado, AR, 71730	
Mailing address:	1945 Smackover Hwy	
(city, state, zip code)	El Dorado, Arkansas, 71730	
County/Parish:	Union County	
Facility Phone Number	870-918-3875	
Facility Contact:	Craig Bonsall (Operator)	Neil Walker (Representative)
	neil@wesoilgas.com	
FRS Number:	NA	
Identification/Permit Number:	ARU002198	
Media Identifier Number:	NA	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Chelsey Sherwood	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Michael Blaha	EPA/Region 6 ECDW	Enforcement Officer/Inspector
Tamara Griffin	EPA/Region 6 ECDW	Enforcement Officer/Inspector
EPA Lead Inspector Signature/Date		1/31/2024
	Chelsey Sherwood	Date
Supervisor Signature/Date		
	Jeanne Eckhart (acting Chief Mitty Garcia)	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Chelsey Sherwood, Michael Blaha, and Tamara Griffin arrived at Neilco (4063) 3G Energy, Frost F3 Tank Battery, located off Old Reed Place Road (33.2465, -92.60204) at 12:37PM on 12/12/2023 for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on Neilco (4063) 3G Energy, Frost F3 Tank Battery which contains 2 150-gallon oil tanks and one heater treater.

Section II - OBSERVATIONS

I observed the facility sign, secondary containment, oil tanks, heater treater, and pipes located at the facility, see Appendix 1 (photo log), photo No. 1 and photo No. 2 for additional GPS location and photo metadata, see Appendix 1.

I observed no cap on the oil tank valve, see photo No. 2.

I observed a low spot in the secondary containment berm, see photo No. 3.

I observed leaking from heater treater.

Section III – AREAS OF CONCERN

No closing conference was held due to no Neilco (4063) 3G Energy staff being present during the inspection. Areas of concern at the time of the inspection include: 1) secondary containment berm was low and should be built back up; 2) no cap on oil tank valve; and 3) active leaking from the heater treater.

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representatives over the coming weeks and months to ensure areas of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photo Log – 3 photos taken 12/12/2023

Appendix 1

Photograph Log

3 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 33.2465, -92.60204		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: 6193

Orientation: E

Date of Photo: 12/12/2023

Time of Photo: 12:40 PM

Latitude: 33.246580

Longitude: -92.602028

Photographer: Chelsey Sherwood

Description: This photo was taken looking E at the facility showing the facility sign.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 33.2465, -92.60204		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: 6194

Orientation: W

Date of Photo: 12/12/2023

Time of Photo: 12:43 PM

Latitude: 33.246589

Longitude: -92.601933

Photographer: Chelsey Sherwood

Description: This photo was taken looking W at the facility showing overall facility overview.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: 33.2465, -92.60204		
City: El Dorado	County/Parish: Union	State: Arkansas



Photo File Name: 6195

Orientation: N

Date of Photo: 12/12/2023

Time of Photo: 12:45 PM

Latitude: 33.246494

Longitude: -92.602026

Photographer: Chelsey Sherwood

Description: This photo was taken looking N at the facility showing a low spot in the secondary containment berm.