

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	4	3
Year-Month-Day:					2	0	2	4	-	0	4	-	3	0	
EPA Permit # (or RA):					F	L	I	0	0	1	4				
					Page		1		Of		2				
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 2:58 pm															
End Time: 3:00 pm															
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC														
	Street Address: 5415 Oil Plant Rd														
	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Nature of Business: oil and gas production														
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702														
	Email:														
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319														
	O/O Mailing Address: 5415 Oil Plant Rd														
Well Data from File	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Well Name & #: St. Regis SWDS #9-5 API No. 09-113-20199 PA No. 311641														
	Well Type (see table): Produced Water Disposal (PWD) State Permit: OG_1078														
	Latitude (°N): 30.95714171 Longitude (°W): -87.1846328 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD: 6743' ☐ Other: surface casing 10 3/4" at 2324'														
	Total Depth (ft): 6786' Inner Casing Size (in): 7" 6786' Tubing Size (in): 4 1/2" at 6240' Packer Depth (ft): 6320'														
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) 6375' Bottom(ft): 6612' Max. Injection Pressure (psig): 1800 psi														
Field Measurements and Observations	Latitude (°N): 30.95709 Longitude (°W): -87.18429 Elevation (ft):														
	EPA GPS ID: S75332 Well Status (see table): TA If not Active, Reported Date Last Active: 2/23/16														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values):														
	DANGER sign is posted: H2S May Be Present...Hazardous Operations...Authorized Personnel Only...														
	An identification sign was posted at the injection well. Tubing gauge: 200 psi														
	Near the tubing gauge was a metal sign showing the Production gauge: 0 psi ?														
	maximum injection pressure is 1800 psi. Surface gauge: 0 psi														
	Pressure from the formation was retained within the Flow line gauge:														
tubing and casing of the injection well. There is some corrosion of metal railings, piping and valves.															
See reverse for additional observations, comments and photo log															
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN								Signature:							
Digitally signed by CAROL CHEN Date: 2024.06.20 21:34:55 -04'00'								Version 2018-04-18							

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 4 3									
Year-Month-Day: 2 0 2 4 - 0 4 - 3 0														
EPA Permit # (or RA): F L I 0 0 1 4														
Page 2 Of 2														
Field Measurements and Observations (Cont.)	(Cont.)													
	St. Regis SWDS #9-5 OG_1078 API No. 09-113-20199													
	Photo Log	Photographer: EPA Camera ID:												
Photo ID: RIMG0154 Time: 2:57 pm Lat (°N): 30.957015 Long (°W) -87.184278														
Description: injection well, well identification sign and DANGER sign posted: H2S May Be Present...Hazardous...														
Photo ID: RIMG0155 Time: 2:58 pm Lat (°N): 30.95709 Long (°W) -87.18429														
Description: surface gauge and production gauge														
Photo ID: RIMG0156 Time: 2:58 pm Lat (°N): 30.95705 Long (°W) -87.18428														
Description: tubing gauge shows 200 psi from the underground pressure of the formation														
Photo ID: Time: Lat (°N): Long (°W)														
Description:														
Photo ID: Time: Lat (°N): Long (°W)														
Description:														
Photo ID: Time: Lat (°N): Long (°W)														
Description:														
UIC Inspector					UIC Inspector									
Name: Carol Chen					Name:									
Signature: CAROL CHEN					Signature:									
Digitally signed by CAROL CHEN Date: 2024.06.20 21:35:20 -04'00'					Version 2018-04-18									