

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 1: Front gate secured with Danger signs.

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 2: Main warehouse/ loading docks.

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 3: New Parts washer solvent and product inside the main warehouse.

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 4: One (1) 55-gallon closed SAA drum of debris labeled “Hazardous Waste” and marked with an indication of hazard for flammability and toxicity.

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 5: One (1) 55-gallon closed SAA drum of PPE and rags labeled “Hazardous Waste” and marked with an indication of hazard for flammability and toxicity.

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 6: One red 55-gallon drum and spent solvent stored in one of the wet dumpsters.

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 7: Non-hazardous waste container storage (used oil and used oil filters).

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 8: One (1) 55-gallon SAA closed drum of used oil samples from purges of material, labeled “Hazardous Waste”, and marked with an indication of hazard.

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 9: Container Storage Area (Hazardous Waste Container Storage/ 10-day).

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 10: Container Storage Area (Hazardous Waste Container Storage/ 10-day).

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 11: One (1) 15,000-gallon permitted AST for waste solvent, labeled with the words “Hazardous Waste”, and marked with a NFPA diamond as an indication of hazard

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 12: The waste solvent AST lines and associated equipment (flanges, pumps, valves, and, end caps) are inspected daily for leaks and are tagged as required by 40 CFR 264 Subpart BB.

Safety-Kleen Systems, Inc.
RCRA CEI Photographs
Taken by Kayla Acosta, EPA
01/25/2022
(Olympus Tough Digital Camera #S75903)



Photo 13: The waste solvent AST lines and associated equipment (flanges, pumps, valves, and, end caps) are inspected daily for leaks and are tagged as required by 40 CFR 264 Subpart BB.