


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:35 AM


Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6343620463604, -71.5701264179432

Photos:



Description: Retention pond


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:33 AM


Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6348461283976, -71.5703190107307

Photos:



Description: Tend to sediment accumulation


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:32 AM

Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6348164905089, -71.5704834317173

Photos:



Description: Area to tend to remove sediment


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:29 AM


Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6344395487394, -71.57087645199

Photos:



Description: Collects water from catch basins on site


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:25 AM

Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6329648778398, -71.5708068780272

Photos:



Description: Wells


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:24 AM

Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6326778675467, -71.5705664595257

Photos:



Description: Stabilized slope behind foundation


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:21 AM

Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.631445717601, -71.5703991391244

Photos:



Description: Retention pond gutter drain


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:20 AM


Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6313173554893, -71.5705545396561

Photos:



Description: Riprap


# Field Photo Report

**Submitted By:** stougas\_EPA

**Submitted Time:** April 16, 2024 10:19 AM

Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6311555486414, -71.5704767773979

Photos:



Description: Back of house stabilized


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:14 AM

Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6309644879389, -71.5693354602211

Photos:



Description: Planning to seed asap


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:12 AM

Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6314104548455, -71.5691253534615

Photos:



Description: Geogrid on slope


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:10 AM


Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6317923499048, -71.5692118440208

Photos:





Description: Swale and retention pond


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:07 AM


Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.632362352873, -71.569373381436

Photos:



Description: Retention pond by second crossing


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 10:04 AM

Project: The Village at Shepley Hill, Groton, MA


If "other":



Location: 42.6333658748465, -71.5685301540147

Photos:





Description: Catch basin leads to retention pond


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 9:58 AM

Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6339052393887, -71.5679323064352

Photos:



Description: Catch basins at entrance drain into this detention pond


# Field Photo Report

**Submitted By:** stougas\_EPA

**Submitted Time:** April 16, 2024 9:57 AM


Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.634023886672, -71.5673573044283

Photos:



Description: Storm drain control


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 9:56 AM


Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6342091524519, -71.5666236466366

Photos:



Description: Crossing 1


# Field Photo Report

Submitted By: stougas\_EPA

Submitted Time: April 16, 2024 9:53 AM

Project: The Village at Shepley Hill, Groton, MA

If "other":



Location: 42.6342340898958, -71.5666339210369

Photos:



Description: Site sign