

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	03/27/2024	Time	11:55
Inspection Due	2019-06-12T00:00:00Z	Operator Representative	Smith Petroleum, LLC		
Operator Info	Smith Petroleum, LLC 507 W. Main St; P.O. Box 134 Barnsdall, OK 74002-0134 Phone: 918-638-1301	Inventory ID	OS3706000		
		API Well No			
		Lease Name	Quapaw		
		Well ID	1W		
Location	SE 19 25N 11E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.622312	Longitude	-96.155671		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Smith Petroleum, LLC		
Inspect No.		Date Last MIT	11/18/1994	Last Test Result	Acceptable
Casing	4.5	Tubing		USDW	
Monitoring Device Elected	N	Tubing s		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 484
FLM Canister Pressure		Actual Pressure	0		Max Volume
Lease Status	Active	Determined?	Open Hole		Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level	1045		
Barrel Fluid Level (%)		Determined?	Echo Meter		
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	At the time of the inspection, the well was overdue for MIT. Inspector observed the fluid level to be 1045 feet below the top of the tubing.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.622312, -96.155671		
City: Barnsdall	County/Parish: Osage	State: Oklahoma



Photo File Name: DSCN

Orientation: NNE

Date of Photo: 03/27/2024

Time of Photo: 10:52 AM

Latitude: 36.622312

Longitude: -96.155671

Photographer: Matthew Allen

Description: This was well OS3706000 at the time of the inspection. The fluid level was observed to be 1045 feet below the tubing valve.