

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	02/27/2025	Time	15:55
		Operator Representative	CapturePoint, LLC		
Operator Info	CapturePoint, LLC 1101 Central Expwy S., Suite 150 Allen, TX 75013 Phone: 832-300-8221	Inventory ID	OS0751000		
		API Well No			
		Lease Name	SBU		
		Well ID	R-W9		
Location	SW 10 25N 06E	Status	Inactive	Well Type	Enhanced Recovery
Latitude	36.656191	Longitude	-96.653177		
Inspection Reason	Plugging Witnessed	Responsible Company at Time of Inspection	CapturePoint, LLC		
Inspect No.		Date Last MIT	10/26/1988	Last Test Result	Fail
Casing	7	Tubing		USDW	
Monitoring Device Elected	N	Tubings		Annulus	AUTHORIZED
Monitoring Device		Fittings	N	N	Max Pressure 768
FLM Canister Pressure		Actual Pressure			Max Volume
Lease Status	Active	Determined?			Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	N	Injection Rate (bpd)			
Injecting	N				
Inspection Comments	Inspector observed completed surface restoration. Inspector previously observed well plugging operations in accordance with EPA approved plugging procedures.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log 2 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.656191, -96.653177		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: IMG_0092

Orientation: NW

Date of Photo: 2/27/2025

Time of Photo: 3:57 PM

Latitude: 36.656191

Longitude: -96.653177

Photographer: Matthew Allen

Description: This was the well sign for well OS0751000, which had been plugged in accordance with the EPA approved plugging procedures.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: 36.656191, -96.653177		
City: Burbank	County/Parish: Osage	State: Oklahoma



Photo File Name: IMG_0093

Orientation: NW

Date of Photo: 2/27/2025

Time of Photo: 3:57 PM

Latitude: 36.656191

Longitude: -96.653177

Photographer: Matthew Allen

Description: This was the location of well OS0751000 with the well cut off and capped 3' below the land surface.