

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	7	9
Year-Month-Day:					2	0	2	4	-	0	5	-	0	1	
EPA Permit # (or RA):					F	L	I	0	0	5	1				
					Page		1		Of		2				
Inspector(s): Carol Chen (lead), Carla Foy Start Time: 10:44 am End Time: 10:53 am															
Facility Contact Information	Facility Name: Maverick Natural Resources, LLC (Breitburn Operating, LP)														
	Street Address: 5415 Oil Plant Rd														
	City: Jay County: Santa Rosa State: FL Zip: 32565														
	Nature of Business: oil and gas production														
	Facility Owner/Operator: Maverick Natural Resources, LLC Phone: 850-675-1702														
	Email:														
	Facility Contact (if different): Al Jones, Plant Superintendent Phone: 251-227-3319														
	O/O Mailing Address: 5415 Oil Plant Rd														
City: Jay County: Santa Rosa State: FL Zip: 32565															
Well Data from File	Well Name & #: Douglas Polk Etal #41-1 API No. 09-113-20154-01														
	Well Type (see table): NI State Permit: OG_882														
	Latitude (°N): 30.9518965 Longitude (°W): -87.14198296 Elevation (ft):														
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing														
	PBTD: 15762' ☐ Other: conductor csg 16" @101', surface csg 9 5/8" @3806'														
	Total Depth (ft): 15839' Inner Casing Size (in): 7" 15836' Tubing Size (in): has a 3 1/2" production tubing														
Field Measurements and Observations	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) Bottom(ft): Max. Injection Pressure (psig):														
	Latitude (°N): No GPS 000 Longitude (°W): No GPS 000 Elevation (ft):														
	EPA GPS ID: SC8284 Well Status (see table): NI If not Active, Reported Date Last Active:														
	Nature of Injected Fluid(s) if any:														
	General Condition of the Well Site:														
	Notes & Comments (include discrepancies from database values): Not Injecting (NI) status; is a shut-in producer. This well is a producer, not an injection well, although has a draft permit with EPA.														
	Tubing Gauge: 0 psi														
	Production Gauge: 0 psi														
	Surface Gauge: not visible														
	See reverse for additional observations, comments and photo log														
UIC Inspector								UIC Inspector							
Name: Carol Chen								Name:							
Signature: CAROL CHEN Digitally signed by CAROL CHEN Date: 2024.06.20 21:55:48 -04'00'								Signature:							
Version 2018-04-18															

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	7	9
	Year-Month-Day:	2	0	2	4	-	0	5	-	0	1
	EPA Permit # (or RA):	F	L	I	0	0	5	1			
		Page					2	Of	2		

[illegible]

Photographer: Carla Foy EPA Camera ID: SC8284

Photo ID: DSCN1397 Time: 10:51 am Lat (°N): No GPS 000 Long (°W) No GPS 000

Description: Well identification sign at the entrance of the property

Photo ID: DSCN1398 Time: 10:52 am Lat (°N): No GPS 000 Long (°W) No GPS 000

Description: Production well, identification sign, DANGER sign: H₂S May be Present...

Photo ID: DSCN1399 Time: 10:53 am Lat (°N): No GPS 000 Long (°W) No GPS 000

Description: production gauge reads 0 psi and surface gauge does not show a visible reading

Photo ID: DSCN1400 Time: 10:53 am Lat (°N): No GPS 000 Long (°W) No GPS 000

Description: tubing gauge reads 0 psi

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

UIC Inspector
Name: _____
Signature: _____