

Leak Detection and Elimination Sheet

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
3-23-02	6036	GC No. 1		EMISSION RECOVERY SYSTEMS UPSTAIRS AND DOWNSTAIRS	100ppm	NO	O-Ring leaking on Ring Seal Filter pack Hydroxide Valve	3-23	DS	DS
1026	AS	728	10.0 8.9							
3-23-02	6037	GC No. 2		LARGE RECOVERY SYSTEMS UPSTAIRS C Compressor Leak at Housing	100ppm	179218	Replaced "C" comp	3-26	MAINT.	BK
12:24	AS	4	6.2							
3-25-02	6038	GC #1	7.7 6.3	North & South UNLOADING STATION EN	10+	NO	Trapped VC in lines, pulled line back down; unhooked	3-2402	EM	EM
0607	AN	2,5								
3-26-02	6039	#1			NO	NO	Nothing Found PUT VC's on Vapor DB			
01:15	B	#5	8.4	RGates	NO	NO	Found nothing			
3-27-02	6040	GC #3	6.6	Found nothing	NO	NO				
09:55	GS									
3-27-02	6041	GC 5	7.4	new middle UNLOADING STATION D. BARR	NO	NO	Nothing Found DB			
2345	CN	2								

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.