

FILE NAME: Garlock (GAR)

DATE: 1971 July 26

DOC#: GAR051

DOCUMENT DESCRIPTION: Ontario Dept of Health - Field Visit Report

I.S.B. File No.

O.S. File No. 2F-57

ONTARIO DEPARTMENT OF HEALTH
ENVIRONMENTAL HEALTH SERVICES BRANCH

365 - 4066

FIELD VISIT REPORT

PART 1

OCCUPATIONAL
HEALTH SERVICE

JUL 26 1971

Memorandum to:

Dr. V. L. Tidey
Chief, Occupational Health Service

Date: July 26, 1971.

From: G. S. Rajhans, P.Eng.

Plant: Garlock of Canada Limited,
66 Jutland Road,
Address: Toronto, Ontario.

Requested by: Mr. A. Cotgreave, I.S.B.

Accompanied by:

Date of Visit: July 23, 1971.

Copies to: Mr. J. McNair (3)
Dr. J. Cowle (2)

Contacts:

Mr. Rostas, Plant Engineer.

Abstract:

This visit was intended to check the dust control measures provided for the braiders and hammer mill. On our arrival at the premises, it was discovered that the plant was shutdown for the summer recess. Nevertheless, a quick tour of the braiding and hammer mill area was made. The writer was very much impressed with the design and fabrication of the new dust control systems at the braiders. The enclosures and ducts appeared to be very well designed. However, no assessment of the adequacy of local exhausts could be made during this visit. The plant will resume the operation in the 1st week of August, 1971. It is therefore recommended that a complete assessment of the dust control system should be made at that time.

RECOMMENDATION

The company should be visited sometime in August.

GSR/jt

G S Rajhans

G. S. Rajhans, P.Eng.

*20 file
GSR*