

**Well Inspection**  
**Osage DNR / Environmental Protection Agency**  
**1201 Elm Street, Suite 500**  
**Dallas, Texas 75270**

|                                  |                                                                                          |                                                  |                     |                         |                                        |
|----------------------------------|------------------------------------------------------------------------------------------|--------------------------------------------------|---------------------|-------------------------|----------------------------------------|
| <b>Inspector</b>                 | Matthew Allen                                                                            | <b>Inspection Date</b>                           | 10/02/2024          | <b>Time</b>             | 13:40                                  |
|                                  |                                                                                          | <b>Operator Representative</b>                   | Calgary Energy, LLC |                         |                                        |
| <b>Operator Info</b>             | Calgary Energy, LLC<br>4444 E. 146th St. N.<br>Skiatook, OK 74070<br>Phone: 918-798-4511 | <b>Inventory ID</b>                              | OS0813000           |                         |                                        |
|                                  |                                                                                          | <b>API Well No</b>                               |                     |                         |                                        |
|                                  |                                                                                          | <b>Lease Name</b>                                | Crossland           |                         |                                        |
|                                  |                                                                                          | <b>Well ID</b>                                   | 2                   |                         |                                        |
| <b>Location</b>                  | SW 04 22N 07E                                                                            | <b>Status</b>                                    | Inactive            | <b>Well Type</b>        | Disposal                               |
| <b>Latitude</b>                  | 36.410663                                                                                | <b>Longitude</b>                                 | -96.5604            |                         |                                        |
| <b>Inspection Reason</b>         | Plugging Witnessed                                                                       | <b>Responsible Company at Time of Inspection</b> | Calgary Energy, LLC |                         |                                        |
| <b>Inspect No.</b>               |                                                                                          | <b>Date Last MIT</b>                             | 03/05/1986          | <b>Last Test Result</b> | Acceptable                             |
| <b>Casing</b>                    | 5.5                                                                                      | <b>Tubing</b>                                    |                     | <b>USDW</b>             |                                        |
| <b>Monitoring Device Elected</b> | N                                                                                        | <b>Tubings</b>                                   |                     | <b>Annulus</b>          | <b>AUTHORIZED</b>                      |
| <b>Monitoring Device</b>         |                                                                                          | <b>Fittings</b>                                  | N                   | N                       | <b>Max Pressure</b> 690                |
| <b>FLM Canister Pressure</b>     |                                                                                          | <b>Actual Pressure</b>                           |                     |                         | <b>Max Volume</b>                      |
| <b>Lease Status</b>              |                                                                                          | <b>Determined?</b>                               |                     |                         | <b>Max Inj Units</b> Barrels Per Month |
| <b>Barrel Monitor Hooked Up?</b> | N                                                                                        | <b>Static Fluid Level</b>                        |                     |                         |                                        |
| <b>Barrel Fluid Level (%)</b>    |                                                                                          | <b>Determined?</b>                               |                     |                         |                                        |
| <b>Flowline Hooked Up?</b>       | N                                                                                        | <b>Injection Rate (bpd)</b>                      |                     |                         |                                        |
| <b>Injecting</b>                 | N                                                                                        |                                                  |                     |                         |                                        |
| <b>Inspection Comments</b>       | Inspector observed surface restoration was completed at the well location.               |                                                  |                     |                         |                                        |
| <b>Inspector Signature</b>       |                                                                                          |                                                  |                     |                         |                                        |
| <b>Supervisor Signature</b>      |                                                                                          |                                                  |                     |                         |                                        |

## Appendix 1

### Photograph Log 1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

## Photograph Log

Photo No. 1

|                               |                      |                 |
|-------------------------------|----------------------|-----------------|
| Location: 36.410663, -96.5604 |                      |                 |
| City: Blackburn               | County/Parish: Osage | State: Oklahoma |



**Photo File Name:** R0010518

**Orientation:** SSE

**Date of Photo:** 10/02/2024

**Time of Photo:** 1:43 PM

**Latitude:** 36.410663

**Longitude:** -96.5604

**Photographer:** Matthew Allen

**Description:** : This was the well location for well OS0813000 after surface restoration had been completed.