

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	2022-03-31T00:00:00Z	Time	13:45
Inspection Due		Operator Representative	Calgary Energy, LLC		
Operator Info	Calgary Energy, LLC 4444 E. 146th St. N. Skiatook, OK 74070 Phone: 918-798-4511	Inventory ID	OS6519000		
		API Well No			
		Lease Name	TO I		
		Well ID	1-13		
Location	SW 24 24N 08E	Status	N	Well Type	Enhanced Recovery
Latitude		Longitude			
Inspection Reason	Responsible Company at Time of Inspection				
Inspect No.		Date Last MIT		Last Test Result	
Casing	5.5	Tubing	2.375	USDW	280
Monitoring Device Elected Monitoring Device FLM Canister Pressure Lease Status Barrel Monitor Hooked Up? Barrel Fluid Level (%) Flowline Hooked Up? Injecting	Tubings	Annulus	AUTHORIZED		
	Fittings		Max Pressure		
	Actual Pressure		Max Volume		
	Determined?		Max Inj Units		
	Static Fluid Level				
	Determined?				
	Injection Rate (bpd)				
Inspection Comments	EPA Inspector witnessed radioactive tracer survey and temperature logs being performed on well as required by new permit. Well 1-13 has effectively demonstrated external mechanical integrity. Additional data collected during these external mechanical integrity tests are under review by Region 6 UIC permitting staff for compliance with required permit conditions . Additional permit requirements must be met to receive Authorization to Inject. This notice of inspection does not grant Authorization to Inject.				
Inspector Signature					
Supervisor Signature					