

Region 6 - Enforcement & Compliance Assurance Division

INSPECTION REPORT

Inspection Date(s):	3/14/24	
Media Program:	Water (CWA)	
Regulatory Program(s)	Water (CWA) Brine Program (Oil & Gas inspection)	
Company Name:	Jerry Langley Oil Company, LLC	
Facility Name:	Flowline spill (off oil lease road off All Gulf Rd)	
Facility Physical Location:	Off oil lease road off All Gulf Rd in Smackover at 33.339567, -92.687617	
(city, state, zip code)	Smackover, AR 71762	
Mailing address:	100 East 7th Street	
(city, state, zip code)	Smackover, AR 71762	
County/Parish:	Union County	
Facility Phone Number	870-725-3042	
Facility Contact:	Jerry Langley jloc58@yahoo.com	Owner / Operator
FRS Number:	N/A	
Identification/Permit Number:	ARU002230	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Michael Blaha	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Uma Lad	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Kerri McCabe (lead)	EPA / Region 6 ECDW	Inspector / Enforcement Officer
EPA Lead Inspector Signature/Date		
	Kerri McCabe	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Michael Blaha, Uma Lad, and Kerri McCabe (lead) arrived at the Jerry Langley Oil Co., LLC / Flowline Release, located off an oil lease road off All Gulf Road at 33.339567, -92.687617; at 0859 on 3/14/24 for an unannounced inspection. No facility representatives were present at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection.

FACILITY DESCRIPTION

EPA conducted an inspection on the Jerry Langley Oil Co., LLC / Flowline Release, which was a release of crude oil and saltwater onto the ground as a result of a broken coupling on a flowline.

Section II - OBSERVATIONS

I observed an active release of crude oil and saltwater from a broken coupling on a flowline, see Appendix 1 (Photographs Log), Photo No. 1 and No. 2. For additional GPS location and photo metadata, see Appendix 1.

After speaking with a facility representative via cellphone, the flowline was repaired; see Photo No. 3 and No. 4.

Section III – AREAS OF CONCERN

No closing conference was held due to no personnel with Jerry Langley Oil Co., LLC being present during the inspection. Areas of concern at the time of the inspection include an active release of crude oil and saltwater onto the ground from a broken coupling on a flowline. The active release of crude oil and saltwater was stopped by Mr. John “Peanut” Thompson of Jerry Langley Oil Co., LLC by repair of the broken coupling on the flowline. Residual crude oil and saltwater, along with the broken section of flowline, remained onsite after the repair was made.

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representative(s) over the coming weeks and months to ensure areas of concern are properly addressed.

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log – 4 photos taken 3/14/24.

Appendix 1

Photograph Log

4 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: Jerry Langley Oil Co, LLC – flowline release off an oil and gas lease road off All Gulf Rd (33.339567, -92.687617)		
City: Smackover	County/Parish: Union	State: Arkansas



Photo File Name: R0010376

Orientation: N-NW

Date of Photo: 03/14/2024

Time of Photo: 0857

Latitude: 33.339567

Longitude: -92.687617

Photographer: Kerri McCabe

Description: This photo was taken looking N-NW at the active flowline release with crude oil and saltwater pooling on the ground at the location.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Location: Jerry Langley Oil Co, LLC – flowline release off an oil and gas lease road off All Gulf Rd (33.339567, -92.687617)		
City: Smackover	County/Parish: Union	State: Arkansas



Photo File Name: R0010377

Orientation: N-NW

Date of Photo: 03/14/2024

Time of Photo: 0857

Latitude: 33.339600

Longitude: -92.687567

Photographer: Kerri McCabe

Description: This photo was taken looking N-NW as an overview of the area impacted by the active flowline release in Photo No. 1.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Location: Jerry Langley Oil Co, LLC – flowline release off an oil and gas lease road off All Gulf Rd (33.339567, -92.687617)		
City: Smackover	County/Parish: Union	State: Arkansas



Photo File Name: R0010407

Orientation: E

Date of Photo: 03/14/2024

Time of Photo: 1250

Latitude: 33.339683

Longitude: -92.687650

Photographer: Kerri McCabe

Description: This photo was taken looking E at the flowline release after it had been repaired by Mr. John "Peanut" Thompson of Jerry Langley Oil Co, LLC; note residual Exploration and Production (E & P) waste on ground.



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Location: Jerry Langley Oil Co, LLC – flowline release off an oil and gas lease road off All Gulf Rd (33.339567, -92.687617)		
City: Smackover	County/Parish: Union	State: Arkansas



Photo File Name: R0010408

Orientation: E-NE

Date of Photo: 03/14/2024

Time of Photo: 1251

Latitude: 33.339583

Longitude: -92.687500

Photographer: Kerri McCabe

Description: This photo was taken looking E-NE at the extent of the flowline repair activities in Photo No. 3.