

Well Inspection
Osage DNR / Environmental Protection Agency
1201 Elm Street, Suite 500
Dallas, Texas 75270

Inspector	Matthew Allen	Inspection Date	02/04/2026	Time	08:30
		Operator Representative	Contango Resources, LLC		
Operator Info	Contango Resources, LLC 1717 South Boulder, Suite 900 Tulsa, OK 74119 Phone: 918-392-3396	Inventory ID	OS2880000		
		API Well No			
		Lease Name	NRU		
		Well ID	20W3		
Location	SE 21 24N 07E	Status	Active	Well Type	Enhanced Recovery
Latitude	36.542391	Longitude	-96.558331		
Inspection Reason	Requested By Compliance Staff	Responsible Company at Time of Inspection	Contango Resources, LLC		
Inspect No.		Date Last MIT	04/22/2019	Last Test Result	Acceptable
Casing	5.5	Tubing		USDW	547
Monitoring Device Elected	N	Tubings		Annulus	
Monitoring Device		Fittings	N	N	Max Pressure 694
FLM Canister Pressure		Actual Pressure	0	0	Max Volume
Lease Status	Active	Determined?	Company Gage	Open Value	Max Inj Units Barrels Per Month
Barrel Monitor Hooked Up?	N	Static Fluid Level			
Barrel Fluid Level (%)		Determined?			
Flowline Hooked Up?	Y	Injection Rate (bpd)	358		
Injecting	Y				
Inspection Comments	Inspector observed well OS2880000. The well was connected and injecting at 355bbls/day. Well was overdue for MIT at the time of the inspection. Great Horned Owls was the new owner/operator at the time of the inspection but the ownership transfer was not completed with EPA.				
Inspector Signature					
Supervisor Signature					

Appendix 1

Photograph Log

1 Photo



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Location: 36.542391, -96.558331		
City: Fairfax	County/Parish: Osage	State: Oklahoma



Photo File Name: R0010778

Orientation: NE

Date of Photo: 2/4/2025

Time of Photo: 9:33AM

Latitude: 36.542391

Longitude: -96.558331

Photographer: Matthew Allen

Description: This was well, OS288000, connected and injecting with a rate of 355 barrels per day. The company pressure gauge displayed 0psi on the tubing.