

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date:	01/15/2026	
Media Program:	Water (CWA)	
Regulatory Program:	Water (CWA) Brine Program (Oil & Gas Inspection)	
Company Name:	Corley Trust, LLC	
Facility Name:	Tatum Tank Battery & Wilson 7 SWD	
Facility Physical Location:	Off Gas Plant Road at 33.353727, -92.69236	
(city, state, zip code)	Smackover, AR, 71762	
Mailing address:	410 W. 6th	
(city, state, zip code)	Smackover, AR 71762	
County/Parish:	Union County	
Facility Phone Number:	870-725-3928	
Facility Contact:	Jeff Corley	Manager
	corleytrust@att.net	
FRS Number:	N/A	
Identification/Permit Number:	ARU002260	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Uma Lad	EPA / Region 6	Inspector / Enforcement Officer
Kerri McCabe	EPA / Region 6	Inspector / Enforcement Officer
Tom McKay	EPA / Region 6	Inspector
Jeff Corley	Corley Trust, LLC	Manager
Aaron McDaniel	Corley Trust, LLC	Pumper
EPA Lead Inspector Signature/Date		
	Uma Lad	Date
Supervisor Signature/Date		
	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Uma Lad, Kerri McCabe, and Tom McKay arrived at the Corley Trust, LLC / Tatum Tank Battery & Wilson 7 SWD, located off Gas Plant Road at 33.353727, -92.69236, at 1:00 PM on 01/15/2026 for an announced inspection. We met with Corley Trust, LLC representatives Jeff Corley, Manager, and Aaron McDaniel, Pumper. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection. EPA previously inspected this facility on 10/07/2024.

FACILITY DESCRIPTION

EPA conducted an inspection on the Corley Trust, LLC – Tatum Tank Battery & Wilson 7 SWD, which consists of three (3) SWD storage tanks, two (2) oil storage tanks, one (1) gun barrel tank and one (1) SWD injection well.

Section II – OBSERVATIONS

I observed the facility, associated signage, storage tanks, gun barrel, SWD injection well, pump and associated piping, see Appendix 1, Photo No. 1 through No. 5.

Section III – AREAS OF CONCERN

There were no areas of concern at the time of the inspection.

Section IV – FOLLOW UP

Inspector will provide the completed inspection report to the company representatives.

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log – 5 photos taken 01/15/2026.

Appendix 1

Photograph Log

5 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Facility/Location:		Corley Trust, LLC / Tatum Tank Battery & Wilson 7 SWD off Gas Plant Road at 33.353727, -92.69236					
City:	Smackover	County:	Union	State:	AR	Direction:	SW
Filename:	R0011343.JPG	Photo Date:		01/15/2026		Time:	13:02:04
Photographer:	Uma Lad			Witness Name:		Kerri McCabe /Tom McKay	



Description:	This photo was taken facing southwest and shows the facility sign.		
Latitude:	33°21'13.728" N	Longitude:	92°41'32.58" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Facility/Location:		Corley Trust, LLC / Tatum Tank Battery & Wilson 7 SWD off Gas Plant Road at 33.353727, -92.69236						
City:	Smackover	County:	Union	State:	AR	Direction:	SW	
Filename:	R0011344.JPG	Photo Date:		01/15/2026		Time:	13:02:37	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe /Tom McKay		



Description:	This photo was taken facing southwest and shows a facility overview.		
Latitude:	33°21'13.524" N	Longitude:	92°41'32.538" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Facility/Location:		Corley Trust, LLC / Tatum Tank Battery & Wilson 7 SWD off Gas Plant Road at 33.353727, -92.69236						
City:	Smackover	County:	Union	State:	AR	Direction:	SSW	
Filename:	R0011345.JPG	Photo Date:		01/15/2026		Time:	13:03:31	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe /Tom McKay		



Description:	This photo was taken facing south-southwest and shows the transfer/load lines with catchment buckets at the facility.		
Latitude:	33°21'13.98" N	Longitude:	92°41'32.01" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Facility/Location:		Corley Trust, LLC / Tatum Tank Battery & Wilson 7 SWD off Gas Plant Road at 33.353727, -92.69236						
City:	Smackover	County:	Union	State:	AR	Direction:	SW	
Filename:	R0011346.JPG	Photo Date:		01/15/2026		Time:	13:06:29	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe /Tom McKay		



Description:	This photo was taken facing southwest and shows a side view of the secondary containment berm and tank battery.		
Latitude:	33° 21'13.866" N	Longitude:	92°41'32.484" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 5

Facility/Location:		Corley Trust, LLC / Tatum Tank Battery & Wilson 7 SWD off Gas Plant Road at 33.353727, -92.69236						
City:	Smackover	County:	Union	State:	AR	Direction:	S	
Filename:	R0011347.JPG	Photo Date:		01/15/2026		Time:	13:07:53	
Photographer:	Uma Lad			Witness Name:		Kerri McCabe /Tom McKay		



Description:	This photo was taken facing south and shows the secondary containment discharge valve at the facility.		
Latitude:	33°21'14.46" N	Longitude:	92°41'32.34" W