

BRANCHES DEPARTMENT - PLANT REQUISITIONS

January 29, 1960

3948 Dayton, O. #1072 - New Branch Installation Expense - carpentry, painting, etc.	5,663.97
3980 Haddonfield, N. J. #5071 - New Branch Installation Expense - electrical work, etc.	4,568.54
3993 Madison, Wisc. #3067 - New Branch Installation Expense - sign erection, etc.	5,028.76
4017 Tulsa, Okla. #6333 - 1 Avon Electric Heater	22.90
4018 West Palm Beach, Fla. #2396 - 6 sections 18" x 36" x 7'3" steel shelving	81.00
4019 Prichard, Ala. #2655 - 1 ea. #313 Manager's Desk, #281 Manager's Chair	110.90
4020 Bradenton, Fla. #2362 - 1 ea. Dedco Power Mixer, 1 Sq. can Adapter, 1 weight scale	228.00
4021 Forrest City, Ark. #6058 - 6 sections steel shelving with 3 shelves per unit	58.26
4023 El Dorado, Ark. #7335 - 1 new 1960 Ford $\frac{1}{2}$ ton Truck, less discount, plus lettering	1,939.08
4024 Patchogue, N. Y. #4770 - 1 special plexiglas illuminated sign, completely installed	1,713.00
4025 Cleveland, O. #1283 - 1 #30 1-gallon paint conditioner	110.50
4026 Charleston, W. Va. #1201 - 1 Hand Truck	12.37
4027 Tulsa, Okla. #6078 - New Branch Installation Expense - carpentry, facia sign, etc.	5,888.19
4028 Arlington, Va. #5952 - 1 new tire for Branch truck	50.61
4029 Ocean City, N. J. #5015 - Paint exterior storefront, repaint facia & wall signs	87.50
4030 Pascagoula, Miss. #7912 - Painting interior & exterior, carpentry work	799.00
4031 Long Beach, Calif. #8506 - Repairs to electric stick-out sign	50.77
4032 Merced, Calif. #6616 - 1 5-gallon can crimper	80.00
4033 Hamilton, O. #1158 - Paint ceiling, walls and trim	180.00
4034 Idaho Falls, Idaho #8016 - Carpentry work to repair & rebuild warehouse shelving	120.00
4035 Lufkin, Tex. #7744 - Remodeling Expense - carpentry work, fluorescent fixtures, etc.	2,823.50
4036 Toledo, O. #1181 - Paint ceiling and walls and fixtures	300.00
4037 Roanoke, Va. #5255 - Repair and repaint delivery truck, reletter truck	193.00
4038 Hazard, Ky. #1074 - Carpentry work required to convert old wrapping counter to stationery supply cabinet	87.00
4039 Greenville, S. C. #2310 - Repairs to delivery truck, 2 new tires	71.90
4040 Portland, Ore. #8613 - Overrun on P. R. #3298 - install service door & signal alarm	89.00
4041 Cleveland, O. #1909 - 1 National Manually-Operated Adding Machine	138.00
4042 Lemoyne, Pa. #5511 - Repairs to adding machine transferred to Lafayette Hill, Pa.	59.00
4043 Portland, Me. #4213 - 1 National Manually-Operated Adding Machine	138.00
4044 San Jose, Calif. #8018 - 1 Pedestal Base for paint conditioner	21.20
4045 Des Moines, Ia. #3578 - 1 Display Table	72.00
4046 Danbury, Conn. #1169 - 1 Miller Double-can Paint Shaker w/timer and base	143.98
4047 Denison, Tex. #7431 - Build 2 storage shelves and install pegboard. Install electrical outlet on sales floor	80.00
4048 St. Paul, Minn. #3256 - 1 Hand Truck	12.37
4049 Oak Lawn, Ill. #3858 - Remodeling Expense - painting, electrical work, carpentry, etc.	2057.00
4050 Columbus, O. #1075 - New Branch Installation Expense - sign erection, misc., etc.	4,798.37
4051 Oil City, Pa. #1168 - Improvement Expense - Install tile floor, paint fixtures, etc.	551.20
4052 Chicago, Ill. #3792 - 2 units standard wall shelving	181.20
4053 East Aurora, N. Y. #1270 - 1 Window Shade Cutter	49.50
4054 Beaver Dam, Wisc. #3003 - Paint walls and ceiling	115.00
4055 Oklahoma City, Okla. #6025 - 1 Wheeldex Cub File	18.50
4056 Oakland, Calif. #8510 - Emergency Repairs to furnace	66.51
4057 Waynesville, N.C. #5018 - Replace 2 plate glass windows	50.30
4058 Faribault, Minn. #3037 - 2 4-tube 4' fluorescent fixtures, installation	69.00
4059 Minot, N. D. #3380 - Paint walls, ceiling and fixtures	150.00
4060 Walnut Creek, Calif. #8033 - 1 #30 1-Gallon Paint Conditioner w/Pedestal Base	140.70
4061 Oshkosh, Wisc. #3183 - 1 #393 Cashier's Desk	102.50
4062 Denver, Colo. #6428 - 1 ea. #393 Cashier's Desk, 1 #281 Manager's Chair	128.40
4063 Milford, Conn. #4070 - 10 sections steel shelving	135.00
4064 Youngstown, O. #1547 - 1 sec. studio shelving, 6 sec. steel shelving, paint ceiling and walls	346.00
4065 Chelsea, Mass. #1103 - New Branch Installation Expense - painting, signs, etc.	4,615.57
4066 Woburn, Mass. #4104 - New Branch Installation Expense - carpentry, sign erection, etc.	4,881.43
4067 Tampa, Fla. #2325 - Recap two tires and purchase one new tire	81.06

0007-SWP-000025771A

N 25115

BRANCHES DEPARTMENT - PLANT REQUISITIONS

January 29, 1960
(Continued)

h068 Nashville, Tenn. #2319 - 1 new 1960 Chevrolet 1-ton Truck, less fleet discount, plus lettering	\$ 2,541.90
h069 Pontiac, Mich. #1877 - 12 4-tube 8' fluorescent fixtures, 4 pr. end plates	240.00
h070 Washington, Pa. #1006 - Remodeling Expense - electrical work, interior painting, etc.	2,660.00
h071 Steubenville, O. #1021 - 1 hand truck	12.37
h072 Macon, Ga. #2331 - Cost of repairing and repainting neon stick-out sign	115.00
h073 Idaho Falls, Ida. #8016 - Cost of improving Branch lighting	135.00
h074 Newton, Kans. #6003 - 1 desk lamp	16.95
h075 Atlanta, Ga. #2033 - Cost of converting used under-canopy sign to read "S-W"	92.44
h076 Biloxi, Miss. #7383 - Recap 3 tires, repair, repaint & reletter truck	156.69
h077 Vicksburg, Miss. #7367 - Paint ceiling, walls and fixtures	345.00
h078 Hayward, Calif. #8571 - Paint interior walls	61.40
h079 Little Rock, Ark. #6312 - Remodeling Expense - install tile floor, electrical, etc.	1,963.00
h080 Lafayette, Ind. #3893 - 1 National Manually-Operated Adding Machine	138.00
h081 Santa Ana, Calif. #8509 - 1 MM-52 Stick-Out Sign, 1 MM-5-26 fascia sign, erection	970.00
h082 Little Rock, Ark. #6586 - Repairs to air conditioner	54.33
h083 Chattanooga, Tenn. #2305 - Cost of raising sidebeds and installing barricade behind cab in new delivery truck	75.00
h084 Jonesboro, Ark. #6681 - Remodeling Expense - sign erection, painting, etc.	712.40
h085 Eunice, La. #7019 - Paint Branch exterior	80.00
h086 Orange, Tex. #7750 - Repaint delivery truck, reletter truck	97.00
h087 Sioux City, Ia. #6275 - 2 display tables	144.00
h088 Del Rio, Tex. #7046 - 1 ea. Mitre Machine, Mitre Vise, Point Driver	92.00
h089 Prichard, Ala. #2655 - Emergency repairs to heating system	87.00
h090 Kennett, Mo. #6005 - 1 Oasis Bottlelet Electric Water Cooler	102.00
h091 Worcester, Mass. #1864 - 1 MM-5-5-0 fascia sign, sign erection	1,033.80
h093 Wakefield, Mass. #4652 - Remove old and install new signs	70.00
h095 Houston, Tex. #7022 - 6 2-tube 8' fluorescent fixtures, installation	111.50
h096 Lexington, Ky. #1230 - Paint ceiling and walls	300.00
h097 Cincinnati, O. #1491 - 7 sections steel shelving	91.00
h098 Monessen, Pa. #1786 - Improvement Expense - painting, electrical work, etc.	1,243.60
h099 Washington, D. C. #5870 - 1 4-tube 8' fluorescent fixture, electrical work	61.42
h100 Oakland, Calif. #9550 - 1 Fairbanks-Morse Industrial Platform Scale, 1 agitator	340.00
h101 Greensboro, N. C. #5347 - Repair & repaint stick-out sign, 1 ea. used desk & chair	165.00
h102 Los Angeles, Calif. #9537 - 1 Toastmaster Model 6A2 Electric Heater	22.46
h103 Raleigh, N. C. #5033 - Repairs to illuminated stickout sign	151.65
h104 Hickory, N. C. #5379 - 4 sections steel shelving	54.00
h105 Atlantic City, N. J. #5849 - Repair, repaint and reletter delivery truck	175.00
h106 Stockton, Calif. #8522 - Repairs to neon fascia sign	63.32
h107 Sullivan, Ind. #3386 - 1 Display table	75.00
h108 Milwaukee, Wisc. #3791 - Paint ceiling walls, trim and fixtures	325.00
h109 Tulsa, Okla. #6333 - 1 11" Royal Typewriter plus taxes	243.00
h110 Paoli, Pa. #5004 - 2 8' sections gravity conveyor	57.20
h111 Beaufort, S. C. #2046 - New Branch Installation Expense - carpentry, misc., etc.	4,057.95
h112 Milford, Mass. #4092 - 8 sec. #1 and 4 sec. #4 steel shelving	158.00

TOTAL

\$69,310.22

0007-SWP-000025771B

0007-SWP-000110635