

Region 6 - Enforcement & Compliance Assurance Division
INSPECTION REPORT

Inspection Date:	01/14/2026	
Media Program:	Water (CWA)	
Regulatory Program:	Water (CWA) Brine Program (Oil & Gas inspection)	
Company Name:	Nevada Oil, LLC	
Facility Name:	Irma Nacatoch (Sand) Unit 26-A1 EOR Tank Battery	
Facility Physical Location:	From Willisville, State Highway 371 North, right on Hwy 76, and then right onto an oilfield lease road at 33.545100, -93.218400.	
(city, state, zip code)	Willisville, AR 71730	
Mailing address:	451 North Washington	
(city, state, zip code)	El Dorado, AR 71864	
County/Parish:	Nevada County	
Facility Phone Number	870-862-9950	
Facility Contact:	Michael L. Burns (870-310-1501) hrowan@ecgcpa.com	Person Responsible for Operation
FRS Number:	N/A	
Identification/Permit Number:	ARU002290	
Media Identifier Number:	N/A	
NAICS:	211111	
SIC:	1311	
Personnel participating in inspection:		
Kerri McCabe (lead)	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Uma Lad	EPA / Region 6 ECDW	Inspector / Enforcement Officer
Tom McKay	EPA / Region 6 SEMD	SEE Inspector
Michael Burns	Nevada Oil, LLC	Operations
Dollar Burns	Nevada Oil, LLC	Companion
EPA Lead Inspector Signature/Date	Kerri McCabe	Date
Supervisor Signature/Date	Jeanne Eckhart	Date

Section I – INTRODUCTION

PURPOSE OF THE INSPECTION

EPA Region 6 inspectors Kerri McCabe (lead), Uma Lad, and Tom McKay (for Spill Prevention Control and Countermeasure (SPCC) inspection) arrived at the Nevada Oil, LLC / Irma Nacatoch Sand Unit 26-A-1 EOR Tank Battery ("facility") located from State Highway 371 North, right on Hwy 76, and then right onto an oilfield lease road at 33.545100, -93.218400 in Willisville, Nevada County, Arkansas; at 0945 on 01/14/2026 for an announced inspection. Mr. Michael Burns represented the facility at the time of the inspection. The inspection was conducted by the authority of the Clean Water Act (CWA) to determine compliance with Environmental Protection Agency (EPA) regulations. There were no other federal, state, or local agency representatives present at the time of the inspection. This facility was last inspected by Inspector Kerri McCabe on 03/05/2025 under the Brine Program.

FACILITY DESCRIPTION

EPA conducted an inspection on the Nevada Oil, LLC / Irma Nacatoch Sand Unit 26-A-1 EOR Tank Battery facility, which contains one (1) tank for saltwater storage and one (1) Class II enhanced oil recovery (EOR) injection well.



Map 1. Aerial imagery (Google Earth dated 08/03/2023) of the Nevada Oil, LLC / Irma Nacatoch Sand Unit 26-A-1 EOR Tank Battery facility.

Section II – OBSERVATIONS

I observed the facility signage, tank battery, pipes and valves, storage tanks, and separators/treaters; see Appendix 1 (Photographs Log), see Photos No. 1 and No. 2. For additional GPS location and photo metadata, see Appendix 1.

I observed the sump area and sump pump inside secondary containment with loose crude oil, Photo No. 3.

I observed the containment berm that Nevada Oil, LLC personnel extended since the 03/05/2025 inspection to contain the total volume of the saltwater tank, see Photo No. 4.

Section III – AREAS OF CONCERN

EPA Region 6 inspectors Kerri McCabe, Uma Lad, and Tom McKay held a closing conference with Mr. Michael Burns with Nevada Oil, LLC after the inspection. The one (1) area of concern under the SPCC rule at the time of the inspection is:

- Loose crude oil and saltwater inside secondary containment, 40 CFR 112.9(b)(1) (Photo No. 3).

Section IV – FOLLOW UP

Inspector will conduct follow-up phone calls with the company representative(s) over the coming weeks and months to ensure areas of concern are properly addressed. SEE Inspector Tom McKay will address SPCC rule concerns.

Section V – LIST OF APPENDICES

Appendix 1 – Photograph Log – 4 photos taken on 01/14/2026.

Appendix 1

Photograph Log

4 Photos



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 1

Facility/Location:		Nevada Oil, LLC Irma Nacatoch Unit 26-A1 EOR Tank Battery						
City:	Willisville	County:	Nevada County	State:	AR	Direction:	SW	
Filename:	R0011286.JPG	Photo Date:		01/14/2026		Time:	09:52:46	
Photographer:	Kerri McCabe			Witness Name:		Tom McKay		



Description:	Looking WSW, this photo shows the signage at the Irma Nacatoch Sand Unit 26-A1 EOR Tank Battery ("facility").		
Latitude:	33°32'42.09" N	Longitude:	93°13'6.018" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 2

Facility/Location:		Nevada Oil, LLC Irma Nacatoch Unit 26-A1 EOR Tank Battery						
City:	Willisville	County:	Nevada County	State:	AR	Direction:	SW	
Filename:	R0011287.JPG	Photo Date:		01/14/2026		Time:	09:53:26	
Photographer:	Kerri McCabe			Witness Name:		Tom McKay		



Description:	Looking SW, this photo shows an overview of the facility.		
Latitude:	33°32'41.664" N	Longitude:	93°13'5.718" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 3

Facility/Location:		Nevada Oil, LLC Irma Nacatoch Unit 26-A1 EOR Tank Battery						
City:	Willisville	County:	Nevada County	State:	AR	Direction:	SW	
Filename:	R0011289.JPG	Photo Date:		01/14/2026		Time:	09:54:36	
Photographer:	Kerri McCabe			Witness Name:		Tom McKay		



Description:	Looking SW, this photo shows the sump area with the sump pump.		
Latitude:	33°32'41.76" N	Longitude:	93°13'6.036" W



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

Photograph Log

Photo No. 4

Facility/Location:		Nevada Oil, LLC Irma Nacatoch Unit 26-A1 EOR Tank Battery						
City:	Willisville	County:	Nevada County	State:	AR	Direction:	S	
Filename:	R0011290.JPG	Photo Date:		01/14/2026		Time:	09:57:32	
Photographer:	Kerri McCabe			Witness Name:		Tom McKay		



Description:	Looking S, this photo shows the containment berm that Nevada Oil, LLC personnel extended to accommodate the volume of the saltwater storage tank.		
Latitude:	33°32'41.754" N	Longitude:	93°13'7.056" W