

Leak Detection and Elimination Sheet

ABD00147856

Date/ Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verify By:
8-26-01 1520 1555 1635	4943 CN	GC5 #1	8.4 5.2 5.0	RG	0	NO	Nothing Found	8-26	DB	DB
8-26-01 1655 1725	4944 CN	GC5 #1 #2	6.7 10.0 5.9 10.0	DB	0	NO	South Liquid Line Shaft down Leaking	8-26	DB	DB
8-27-01 07:50	4945 KC	GC5 7	— 10	Found nothing HCB #2336						
8-28-01 1215	4946 BN	GC #2 5	7.2 —	Found nothing HCB #2325	0	NO	—	—	—	—
8-28-01 1400	KC 4947	GC #5 7	— 10.68	Hi and Deep Suck Coarse Batch Cilic in Diaphragm - Hopper	52	NO	Cleaned out hopper Out diaphragm batch	8-28	WIL	WIL
8-28-01 1742	4948 BN	GC #1 3	5.4 —	RC LITLX 901217 Liquid valve on Aend of car	15	NO	valve was tightened	8/28	WR	WR

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Molding Report and returned to the Environmental Manager when all sections are completed.

Leak Detection and Elimination Sheet

Date/Time	Leak No./ Written up By:	GC Steam Number(s)	GC Readings	Leak Location	HNU Readings	Notification Written?/ Not. No.	What Repairs Were Made?	Date Repaired	Repaired By:	Repair Verified By:
8-28-01	4949	GC #2	8.5	Nothing Found	0	No	No Readings Found			
1756	BN	9		C. Brownlee						
8-28-01	4950	GC #4	5.7 5.9 10.10	#7 spot North liquid line	25	Yes	Hose disconnected			
1818	SW	3								
8-28-01	4951	GC 5	10.0 6.2	#84 #10 Spot North Liquid DB Lines			Both Hoses disconnected	8-28	DB	DB
1900	CN	2								
8-28-01	4952	GC 5	6.4							
1950	CN	3								
8-28-01	4953	GC #2	5.4	Top of 500	20	NO	Seal threads and tighten pressure gauge PX 500	8-29	CB	CB
0913	BN	7								
8-29-01	4954	GC #5		Hi mol Dump pump Intake Flange.	150	Yes	Tighten Flange	8-29	Em	JS
1433	KC	7	6.0, 7.3, 10							

ABD00147857

This sheet is to be filled out in the event of one(1) reading of five (5) Parts Per Million or more on the any station of any Chronograph.
This sheet is to be distributed as part of the Vinyl Morning Report and returned to the Environmental Manager when all sections are completed.