

10-11-76
have
lock

Dr. Stalleys Inspection

16-9-76

George T. Howell

↳ G.B.

↳ Conoco Womans Comp.

↳ Conoco Mexican

Labs

REPE - SS & EB FOR > Flow.

• Coffee & Creamer & Sugar Containers should be kept covered

SS/Mark Paley/Floor area w/ possibly cover section
at floor w/ Day Glo Orange

Shelves in lab w/ Glass bottles should have bar clip.

Shower West Side - Install Distributer heads?

VCM Bombs - Leaks - Check to make sure
it's don't leak.

~~BREAK ROOM~~

Electrical Outlet Receptacle cover missing Remo MW oven.

VENDING CONTRACTOR - Cleanliness Lacks - MW oven

Drop Ceiling Below Bar Joints

Sky lights are dirty & may best be kept clean by installing
a diffuser panel.

Mineral Deposits on Drinking Fountains Plan + Wides can be
cleaned w/ Metal Cleaner

21PT	ee Tape	ow Dates?
Int'l Centrifuge		
#809		
head		

East Whse

10-4-76

GC Pt D be Moved to Shrink Wrap. Move Old Scrap
Unit Point to Area - Ask Uptain. - OK

S.W. ~~HA~~ Old Scrap

- 3305 Resin RVCN Hi Levels

↳ What Is The Stripping Spec?

- Water Cooler Prairie. B-1

- Fire Ext B-1

- Crushed Flammable liquids Can D-1

Plasticizer

2ND FLOOR - Floor Fan is NOT GUARDED ON
Back Side. - GUARDS MUST NOT ALLOW FINGERS
TO GET THROUGH

COMPOUND

NO DRAINAGE AT #3 FCN CONTROL PANEL.

- Silo # 475 - Drive Belt GUARD NEEDS TO BE ENCLOSED ON BACK SIDE
- Water on ground @ 476 Silo
- GROUND WIRE Broken off on Silo # 474

Dr. Staffy

Coupling
Guard
L-2534
air
connectors
not kept.
in
condition

A

Phthalic Anhydride - Unloading! BAD METHOD

~~Boiler House~~ *

~~Welder~~ - Should be placed outside - Need Flash Curtain

Water Cooler - Polypropylene - Water Type?

~~H₂O TREATMENT POND~~ *

SNOWER - EXTEND TO HIGHER ELEVATION & SUPPORT.
↳ INSTALL BETTER LABEL.

~~H₂SO₄ SIGN~~ EAST OF EAST POND?

ROADBED IS ERODING!

CATALYST BLDG.

SS - Insufficient H₂O Press & Vol.

Wooden Walkways on roofs in dryer bldg.

LABOR R/

① Boom EXT. Still on Paint Crane on D-400R/

② J. HARRING NOT Wearing Safety Glasses

③ Broken H₂ Monomer @ obsolete oil seal unit by walk way @ Rec Area B level.

④ Broken Glass in Pad NW Corner V-11

Compressed Gas Stg. Area Air

Elect. Cords — length perhaps Unneeded

Ventilation problems — fine

oil drums N of Fine pump house — need stg Area — unshielded & covered.

↳ Spray for weeds

↳ West Access to Auction Screens