

TITLE OF PROJ. OR STUDY _____

PROJ. OR STUDY No. _____

SUBJECT C-8 MeetingWORKS 1 of 1COMPUTER ARBDATE 4/91981

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

① RECYCLE TANK

- Boilermakers have no problem w/ installation
- Vandon on schedule
- 900 LV-1 will be located on 2nd level + discharge into 6" line
- Pipe sketching 6" line for project
- Reviewing / revising steel design

② Breathing Air CO2

- All 5 stations installed, most of large hoses (total 9)
- Small (25 ft.) hoses to slip this week

③ No Response from Doughty on what to tell 2 Window cleaning people④ SAMPLE RESULTSWET FINK OPERATORWINANS

3-6	0.17	<i>plugged up unplugged or lost - finish</i>	3-26	0.26
3-13	1.92		3-27	0.51
3-16	0.72		3-30	3.17 (POWDER IN IMPINGER)
3-24	0.20		3-31	<0.1
3-27	0.34		4-1	0.30
3-31	<0.1		4-2	<0.1
4-2	<0.1		4-3	3.38
4-1	<0.1			
1-20	0.18			
2-9	0.20			
2-20	0.18			

⑤ CLEAN ROOM SEALING PROBLEM @ CEILING NOT PAN⑥ DISCUSS PERSONAL PROTECTIVE EQUIPMENT LETTER (Attached)