

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: <table border="1" style="display: inline-table; border-collapse: collapse;"><tr><td>K</td><td>Y</td><td>S</td><td>0</td><td>9</td><td>9</td><td>0</td><td>0</td><td>1</td><td>0</td></tr><tr><td>2</td><td>0</td><td>2</td><td>4</td><td>-</td><td>1</td><td>0</td><td>-</td><td>2</td><td>4</td></tr></table>										K	Y	S	0	9	9	0	0	1	0	2	0	2	4	-	1	0	-	2	4
						K	Y	S	0	9	9	0	0	1	0																				
						2	0	2	4	-	1	0	-	2	4																				
						Year-Month-Day: <table border="1" style="display: inline-table; border-collapse: collapse;"><tr><td>2</td><td>0</td><td>2</td><td>4</td><td>-</td><td>1</td><td>0</td><td>-</td><td>2</td><td>4</td></tr></table>										2	0	2	4	-	1	0	-	2	4										
2	0	2	4	-	1	0	-	2	4																										
EPA Permit # (or RA): <table border="1" style="display: inline-table; border-collapse: collapse;"><tr><td>K</td><td>Y</td><td>I</td><td>0</td><td>4</td><td>2</td><td>0</td></tr></table>										K	Y	I	0	4	2	0																			
K	Y	I	0	4	2	0																													
						Page		1	Of		2																								
Inspector(s): <u>Carol Chen</u> (lead), <u>Lonnie Dorn</u> Start Time: <u>7:56 am</u>																																			
End Time: <u>7:59 am</u>																																			
Facility Contact Information	Facility Name: <u>Logsdon Valley Oil Co., Inc.</u>																																		
	Street Address: <u>105 Bedford Court</u>																																		
	City: <u>Horse Cave</u> County: <u>Hart</u> State: <u>KY</u> Zip: <u>42749</u>																																		
	Nature of Business: <u>oil production</u>																																		
	Facility Owner/Operator: <u>Ms. Ellen Stinson, President</u> Phone: <u>270-537-4288</u>																																		
	Email: <u>estinson@scrtc.com</u>																																		
	Facility Contact (if different): _____ Phone: _____																																		
	O/O Mailing Address: <u>105 Bedford Court</u>																																		
	City: <u>Horse Cave</u> County: <u>Hart</u> State: <u>KY</u> Zip: <u>42749</u>																																		
Well Data from File	Well Name & #: <u>PAYTON #7 East</u>																																		
	Well Type (see table): <u>Class II-R, Enhanced Oil Recovery (EOR)</u> State Permit: <u>55365</u>																																		
	Latitude (°N): <u>37.19390</u> Longitude (°W): <u>-85.77695</u> Elevation (ft): _____																																		
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing																																		
	☐ Other: <u>7" surface casing</u>																																		
	Total Depth (ft): <u>633</u> Inner Casing Size (in): <u>4 1/2"</u> Tubing Size (in): <u>2 3/8"</u> Packer Depth (ft): <u>560</u>																																		
Inj. Zone: ☐ Open Hole; ☐ Perforated; Top(ft) _____ Bottom(ft): _____ Max. Injection Pressure (psig): _____																																			
Field Measurements and Observations	Latitude (°N): <u>000</u> Longitude (°W): <u>000</u> Elevation (ft): _____																																		
	EPA GPS ID: <u>SC8284</u> Well Status (see table): <u>AC</u> If not Active, Reported Date Last Active: _____																																		
	Nature of Injected Fluid(s) if any: <u>Produced Waters (PW)</u>																																		
	General Condition of the Well Site: _____																																		
	Notes & Comments (include discrepancies from database values): _____																																		

	<u>Can hear the trickling sounds of produced waters, flowing under gravity pressure</u>																																		
<u>for enhanced oil recovery. The storage tank is beside the injection well. The injection well</u>																																			
<u>shows corrosion. The annulus pressure gauge is damaged/illegible.</u>																																			

See reverse for additional observations, comments and photo log																																			
UIC Inspector						UIC Inspector																													
Name: <u>Carol Chen</u>						Name: _____																													
Signature: <u>CAROL CHEN</u>						Signature: _____																													
Digitally signed by CAROL CHEN Date: 2024.12.10 17:25:44 -05'00'																																			
Version 2018-04-18																																			

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424				Inspection ID EPA Well ID#: K Y S 0 9 9 0 0 1 0 Year-Month-Day: 2 0 2 4 - 1 0 - 2 4 EPA Permit # (or RA): K Y I 0 4 2 0 Page 2 Of 2												
Field Measurements and Observations (Cont.)	(Cont) PAYTON #7 East Class II-R, Enhanced Oil Recovery (EOR)															
Photo Log	Photographer: Carol Chen EPA Camera ID: SC8284															
	Photo ID: DSCN1501 Time: 7:56 am Lat (°N): 000 Long (°W) 000															
	Description: storage tank															
	Photo ID: DSCN1502 Time: 7:56 am Lat (°N): 000 Long (°W) 000															
	Description: storage tank and injection well															
	Photo ID: DSCN1503 Time: 7:57 am Lat (°N): 000 Long (°W) 000															
	Description: injection well															
	Photo ID: DSCN1504 Time: 7:58 am Lat (°N): 000 Long (°W) 000															
	Description: production well is nearby															
	Photo ID: Time: Lat (°N): Long (°W)															
Description:																
Photo ID: Time: Lat (°N): Long (°W)																
Description:																
UIC Inspector Name: Carol Chen Signature: CAROL CHEN								UIC Inspector Name: Signature:								
Digitally signed by CAROL CHEN Date: 2024.12.10 17:26:08 -05'00' Version 2018-04-18																