

TABLE VI
SOLVENT VAPOR LEVELS
IN
DEPARTMENT 14
VICTOR MANUFACTURING AND GASKET COMPANY
CHICAGO, ILLINOIS

<u>Location of Test</u>	<u>Diacetone Alcohol, P.P.M.</u>	<u>f.l.e.l.</u>
Air sample collected inside plenum for Curtain Coater # 1.	1000 +	20
Air sample collected over conveyor prior to entering Curtain Coater # 1.	320-500	
Air sample collected over Curtain Coater #1.	120	
Air sample collected at inlet to Oven #1.	120-180	
Air sample collected at outlet for Oven #1	100	
Air sample collected at inlet for Curtain Coater # 2.	660	
Air sample collected at outlet behind glass for Curtain Coater # 2.	720	
Air sample collected inside Curtain Coater #2.plenum.		10
Air Sample Collected an inlet to Oven # 2.	180	
Air sample collected at outlet for Oven #2.	60	
Breathing zone air sample collected from inspector at Oven # 2	100	

VMG-31-0000277