

Part A Response

Part A – to be submitted within 24 hours of the incident

Permit Number	BU5453IY
Name Of Operator	AGC Chemicals Europe Ltd
Location Of Installation	Hillhouse International, Thornton Cleveleys, Lancashire
Time and date of the detection	22/03/2023

(a) Notification requirements for any malfunction, breakdown or failure of equipment or techniques, accident or fugitive emission of a substance not controlled by an emission limit which has caused, is causing or may cause significant pollution

To be notified within 24 hours of detection

Date and time of event	17/02/2023
Reference or description of the location of the event	Missed 24-hour effluent sample on 17/01/2023 from W1 Discharge to River Wyre.
Description of where any release into the environment took place	Inline pH and temperature monitoring and no abnormal operations so do not expect any abnormal results.
Substance(s) potentially released	n/a
Best estimate of the quantity or rate of release of substance(s)	n/a
Measures taken, or intended to be taken, to stop any emission	n/a
Description of the failure or accident	Power spike observed at the site on 17/02/2023 (electrical fault at a substation in Penwortham, Preston). Effluent samples have been obtained since this date with no abnormal results.

Name*	
Post	
Signature	
Date	01/03/2023

*authorised to sign on behalf of AGC Chemicals Europe