

Class I and II Well Inspection Form US Environmental Protection Agency – Region 4 Underground Injection Control Program 61 Forsyth Street SW, MC 9T25, Atlanta, Georgia, 30303 Phone: (404)562-9424					Inspection ID	EPA Well ID#: F L S 1 1 3 0 0 3 8 Year-Month-Day: 2 0 2 3 - 0 3 - 2 9 EPA Permit # (or RA): N O N E Page 1 Of 2											
Inspector(s): <u>Carl E. Weller</u> (lead), <u>Carol Chen</u>					Start Time: 12:57 pm End Time: 1:06 pm												
Facility Contact Information	Facility Name: <u>Maverick Natural Resources, LLC (Breitburn Operating LP)</u>																
	Street Address: <u>5415 Oil Plant Rd</u>																
	City: <u>Jay</u> County: <u>Santa Rosa</u> State: <u>FL</u> Zip: <u>32565</u>																
	Nature of Business: <u>oil and gas production</u>																
	Facility Owner/Operator: <u>Maverick Natural Resources, LLC</u> Phone: <u>850-675-1702</u>																
	Email: _____																
Well Data from File	Facility Contact (if different): <u>Al Jones, Plant Superintendent</u> Phone: <u>251-227-3319</u>																
	O/O Mailing Address: <u>5415 Oil Plant Rd</u>																
	City: <u>Jay</u> County: <u>Santa Rosa</u> State: <u>FL</u> Zip: <u>32565</u>																

Field Measurements and Observations	Well Name & #: <u>J. E. Jackson #40-4A</u> API No. <u>0911320100</u> PA No. <u>311598</u>																
	Well Type (see table): <u>Enhanced Oil Recovery (EOR)</u> State Permit: <u>OG_627</u>																
	Latitude (°N): <u>30.95984573</u> Longitude (°W): <u>-87.20001232</u> Elevation (ft): _____																
	Injection Method (check applicable): ☐ Casing Injector; ☒ Tubing & Packer; ☐ Cemented Injection Tubing PBTD: 15778' ☐ Other: <u>surface casing 9 5/8" @3744'</u> BHA Otis WB Packer																
	Total Depth (ft): <u>15828'</u> Inner Casing Size (in): _____ Tubing Size (in): _____ Packer Depth (ft): <u>15510'</u>																
	Inj. Zone: ☐ Open Hole; ☒ Perforated; Top(ft) <u>15656'</u> Bottom(ft): <u>15710'</u> Max. Injection Pressure (psig): <u>4400 psi PW</u> <u>7500 psi N2</u>																
	Latitude (°N): <u>30.95986</u> Longitude (°W): <u>-87.20005</u> Elevation (ft): _____																
	EPA GPS ID: <u>SX8123</u> Well Status (see table): <u>TA</u> If not Active, Reported Date Last Active: <u>1/29/2020</u>																
	Nature of Injected Fluid(s) if any: _____																
	General Condition of the Well Site: _____																
Notes & Comments (include discrepancies from database values):	_____																
	Maximum injection pressure: 7500 psi Nitrogen (N₂), 4400 psi Produced waters (PW).																
	Injection well failed a mechanical integrity test on 1/29/2020. Valves are shut, sealed. Needs workover.																
	Perforations (Smackover Formation):																
	15656' to 15666' (4SPF) 1/15/1974																
	15656' to 15666' (4SPF) 10/28/2012																
	15700' to 15710' (4SPF) 5/01/1974																
	15700' to 15710' (4SPF) 10/28/2012																
UIC Inspector	Name: <u>Carl E. Weller</u>																
	Signature: <u>CARL WELLER (Affiliate)</u> Digitally signed by CARL WELLER (Affiliate) Date: 2023.05.17 10:14:41 -04'00'																
UIC Inspector	Name: <u>Carol Chen</u>																
	Signature: <u>CAROL CHEN</u> Digitally signed by CAROL CHEN Date: 2023.05.15 15:37:57 -04'00'																

Inspection ID	EPA Well ID#:	F	L	S	1	1	3	0	0	3	8
	Year-Month-Day:	2	0	2	3	-	0	3	-	2	9
	EPA Permit # (or RA):	N	O	N	E						
					Page	2	Of	2			

[illegible]

Photographer: Carl E. Weller EPA Camera ID: SX8123

Photo ID: 178 Time: 12:57 pm Lat (°N): 30.95986 Long (°W) -87.20005

Description: sign posted directly on the injection well, closest GPS location

Photo ID: 179 Time: 12:58 pm Lat (°N): 30.95987 Long (°W) -87.20001

Description: photo of injection well, a few feet back

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

Photo ID: _____ Time: _____ Lat (°N): _____ Long (°W) _____

Description: _____

UIC Inspector

Name: Carol Chen

Signature: **CAROL CHEN** Digitally signed by CAROL CHEN
Date: 2023.05.15 15:38:32 -04'00'